СНІ-004133 тм	N 9-NORMAL,NB,104133,SE011 17	120250512 5745	UTC U W TN CERTCERTCERT TRD RAMPBUMPCAM	02 1PBOOKEXFLROTABATT 94/
Ford ford.com	VEHICLE DESCRIPTION EXPLORER PLATINUM R 2025 EXPLORER PLATINUM R 119" WHEELBASE 3.0L ECOBOOST V6 ENGINE 10-SPEED AUTO TRANSMISSIO	CARBONIZEI INTERIOR	SG B88370 D GRAY METALLIC RAY LEATHER SEATS	EPA DOT Fuel Economy and Env Fuel Economy MPG. The best
STANDARD EQUIPMENT INCLUDI EXTERIOR • CLASS III TRAILER TOW PKG • EASY FUEL® CAPLESS FILLER • FRT/RR SKID PLATE ELEMENTS • GRILLE - UNIQUE SATIN • HEADLAMPS - ADAPTIVE LED • LED SIGNATURE LIGHTING • MIRRORS-PWR/HTD/AUTO-FOLD SIG/APRCH LAMP/MEM/AUTODIN • PANORAMIC VISTA ROOF® • PRIVACY GLASS - REAR DOORS • ROOF-RACK SIDE RAILS-SATIN • TAILLAMPS/FOG LAMPS - LED • TRAILER SWAY CONTROL • WIPERS - RAIN-SENSING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 600A OPTIONAL EQUIPMENT/OTHER 3.0L ECOBOOST V6 ENGINE P275/45R21 A/S BSW TIRES BLUECRUISE EQUIP: 1 YEAR PLAN LUX LEATHER PACKAGE 50 STATE EMISSIONS 21" DARK ALLOY ALUM WHLS ULTIMATE PACKAGE MINI SPARE AND JACK KIT	INTERIOR • "EXPLORER" FRNT FLOOR MATS • 110V/150W AC POWER OUTLET • 12.3" LCD DIGITAL CLUSTER • 2ND ROW HEATED SEATS • AMBIENT LIGHTING • AUTO-DIM REARVIEW MIRROR • HTD LTHR WRAPPED STEERING	TOTAL VEHI	WARRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSIST (MSRP) DRMATION	fueleconomy.gov Calculate personalized estimates and compare vehicles
	RAMP ONE CT06 RAMP TWO ITEM #:	CONVOY	L MSRP \$58,710.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit	IFMWK7HC3SGB888370 WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine exh lead, which are known to the State of California to cause cancer
	This label is affixed pursuant to Information Disclosure Act. Gas State and Local taxes are not in options or accessories are not	o the Federal Automobile Isoline, License, and Title Fees, Included. Dealer installed SE011 N	www.ford.com/finance. RB 2X 560 004133 05 01 25	lead, which are known to the State of California to cause cancer a To minimize exposure, avoid breathing exhaust, do not idle the el vehicle in a well-ventilated area and wear gloves or wash your ha For more information go to www.P65Warnings.ca.gov/passenger

1202505125745

