KIP-002859 WA 9-NORMAL, NB, 102859, SE061 <b>7958</b>			CERTCERTCERT TRD RAMPBUMPCAMPBOOKEXFLROTABATT 237	
	CLE DESCRIPTION SUPER DUTY 2025 F350 SRW 4X4 CREW CAB XLT 176" WB STYLESIDE 7.3L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT			California Air Resources Boa Environme
STANDARD EQUIPMENT INCLUDED AT EXTERIOR FOG LAMPS HEADLAMPS - AUTO HIGH BEAM HEADLAMPS - AUTOLAMP (ON/OFF) TOW HOOKS TRAILER BRAKE CONTROLLER TRAILER SWAY CONTROL TRAILER TOW MIRRORS NCLUDED ON THIS VEHICLE DYTIONAL EQUIPMENT PKG.613A '.3L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT T275/70R18E BSW ALL TERRAIN 3.73 ELECTRONIC-LOCKING AXLE FRONT LICENSE PLATE BRACKET 7:4 OFF-ROAD PACKAGE SKID PLATES " ANGULAR BRHT ANDZD STEP BAR 1900# GVWR SURFACE POWER SLIDING REAR WINDOW NTERIOR WORK SURFACE POWER SLIDING REAR WINDOW NTERIOR WORK SURFACE POWER SLIDING ALL FERNATOR AND DUAL ALTERNATOR AND DUAL ALTERNATOR AN	INDEXTRA CHARGE P. 1200 UTLET P. 100CH UP/DOWN DR/PASS WIN AIR COND, MANUAL FRONT CLOTH SUN VISORS CLTH SEATS W/8-WAY PWR DRV PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS UPPER GLOVEBOX STORAGE NO CHARGE 265.00 NO CHARGE S50.00 695.00 190.00 NO CHARGE NO CHARGE NO CHARGE NO CHARGE NO CHARGE NO CHARGE 00 CHARGE	FUNCTIONAL   • FORDPASS™ CONNECT 5GWI-FI   • HILL START ASSIST   • MONO BEAM COIL SPRING FRT   SUSPENSION W/STAB BAR   • PRE-COLLISION ASSIST W/AEB   • REMOTE KEYLESS ENTRY   • SYNC®4	\$57,200.00     IS/OTHER   4,765.00     E & OPTIONS/OTHER   61,965.00	
	RAMP ONE   RL7C   RAMP TWO   ITEM #:   7   This label is affixed pursuant to the Information Disclosure Act. Gasol State and Local taxes are not inclu	r4-5860 O/T 2 Ford Credit ft W e Federal Automobile line, License, and Title Fees,	/hether you decide to lease or finance your ehicle, you'll find the choices that are right or you. See your dealer for details or visit ww.ford.com/finance.	<b>1FT8W3BN4SED59224</b> WARNING: Operating, servicing and maintaining a p vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause can to minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passe

