KII -000250 FL 4-REBILL, NB, 200250, SD162 0142 [CERT[C			ERT[CERT]CERT] TRD [RAMP BUMP CAMP BOOK EXFL ROTA] 1/		
VER VER VER VER VER VER VER VER	ICLE DESCRIPTION SUPER DUTY 2025 F350 DRW 4X4 CREW CAB PLATINUM 176" WB STYLESIDE 6.7L POWER STROKE V8 DIESEL 10-SPEED AUTO TORQSHIFT	EXTERIOR AGATE BLACK INTERIOR BLACK ONYX P	SE C81628 SE C81628 LAT BLUE LEATHE SAFETY/SECURITY • ADVANCETRAC™ WITH RSC® • AIRBAGS - SAFETY CANOPY® • BELT-MINDER CHIME • DRIVER/PASSENGER AIR BAGS • LED CTR HIGH MNT STOP LAM • SECURE PKG 1 YR INCLUDED • SOS POST-CRASH ALERT SYST MARRANTY • 3YR/36,000 BUMPER / BUMPEF • 5YR/60,000 POWERTRAIN • 5YR/60,000 POWERTRAIN • 5YR/60,000 POWERTRAIN • 5YR/60,000 DIESEL ENGINE (MATION S/OTHER • 4,33 • 4,33 • 4,30 • 5,7	 California Air Resources Board Environment These ratings are not directly comparable For information on how to compare Protect the environment. Ch Greenhouse Gas Rating (tailpipe on C- 	
OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.723A 6.7L POWER STROKE V8 DIESEL 10-SPEED AUTO TORQSHIFT LT245/75R17E BSW ALL-TERRAIN 3.55 RATIO LIMITED SLIP AXLE FRONT LICENSE PLATE BRACKET FX4 OFF-ROAD PACKAGE	10,495.00 NO CHARGE 165.00 385.00 NO CHARGE	BASE PRICE TOTAL OPTION TOTAL VEHICLE	MATION \$81,3 S/OTHER 14,3 E & OPTIONS/OTHER 95,7	395.00 305.00 700.00	
	RAMP ONE	TOTAL	MSRP \$97,795.00	0	

RAMP ONE		TOTAL MSRP	\$97,795.00	
RH12			cide to lease or finance your	
RAMP TWO	RAIL	(Ford) vehicle you'll fi	nd the choices that are right ur dealer for details or visit	WARNING: Operating, servicing and mainta vehicle can expose you to chemicals includ lead, which are known to the State of California to
	1TEM #: 24-R085 O/T 2	Ford Credit for you. See you www.ford.com/		
This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		SD162 R RB X 525 000250 04 16 25		To minimize exposure, avoid breathing exhaust, do vehicle in a well-ventilated area and wear gloves of For more information go to www.P65Warnings.ca.

