
KAN-000521 <sub>MI</sub>	47C   651   6B   2   X     LABL   ADJ   COV   PRCS	B10 RAMP BUMP	BR1C88SKA10790	TRANSIT	MAIL	02 486
ford.com	HICLE DESCRIPTION TRANSIT 2025 250 MR CARGO RWD 148" WHEELBASE 3.5L PFDI V6 (GAS) 10-SPEED TRANSMISSION	INTERIO	DR DR WHITE	0790		Resources Board
STANDARD EQUIPMENT INCLUDER EXTERIOR • AUXILIARY FUEL PORT • BODY SIDE MOLDINGS - BLACK • BUMPERS - CARBON BLACK • FULL SIZE SPARE TIRE/WHEEL • HEADLAMP COURTESY DELAY • WIPERS - RAIN-SENSING INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.101A 3.73 NON-LIMITED SLIP AXLE FRONT LICENSE PLATE BRACKET VINYL F/R FLOOR COVERING 9150# GVWR PACKAGE 50 STATE EMISSIONS REVERSE SENSING SYSTEM TOW/HAUL W/ TRAILER WIRING TRAILER BRAKE CONTROLLER LARGE CENTER CONSOLE RUNNING BOARD 2 ADDITIONAL KEYS E-85 FLEX FUEL CAPABLE	AT NO EXTRA CHARGE INTERIOR ASSIST HANDLES - A-PILLAR CENTER CONSOLE NITERIOR LIGHTING - LED LOCKING GLOVE BOX POWERPOINT - 12V (FRONT) STEERING - TILT/TELESCOPIC TACHOMETER NO CHARGE 245.00 NO CHARGE 295.00 205.00 2		SAFETY/SECI   AMPS • 3 POINT SAF   STEER • ADVANCETR   ARNING • AIRBAGS ⊠ F   SAFETY CAN • BRAKES - 4W   NG • SECURILOCH   N/AEB • SOS POST-C   T • TIRE PRESSU   VN • 3YR/36,000 E   • SYR/60,000 F	3YR/36,000 BUMPER / BUMPER 5YR/60,000 POWERTRAIN 5YR/60,000 ROADSIDE ASSIST (MSRP) 10N 11ER \$50,800.00 11ER 1,625.00 0PTIONS/OTHER 52,425.00		
	RAMP ONE CM58 RAMP TWO	CONVOY	Whether you decide	<b>54,520.00</b> to lease or finance your he choices that are right aler for details or visit	Crash Rea Based on the risk of injury in a Rollover Based on the risk of rollover in Star ratings range from 1 to Source: National High www.st	Not Rat in a single-vehicle crash. to 5 stars ( ★ ★ ★ ★ ), wit way Traffic Safety Adminis afercar.gov or 1-888-327-42 1FTBR1C88SKA10790
	This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not in options or accessories are not	the Federal Automobile soline, License, and Title Fees, cluded. Dealer installed	SPECIAL O R189 R 6B 2X 520 00052	nce. RDER	Vehicle can expose you lead, which are known to the Si To minimize exposure, avoid br vehicle in a well-ventilated area For more information go to ww	servicing and maintaining a pass to chemicals including engine ex tate of California to cause cance reathing exhaust, do not idle the a and wear gloves or wash your h w.P65Warnings.ca.gov/passenge



- ated ated
- ated

vith 5 being the highest. nistration (NHTSA). 4236



assenger vehicle, pickup truck, v e exhaust, carbon monoxide, phtl ncer and birth defects or other reproductive narm, he engine except as necessary, service your ur hands frequently when servicing your vehicle. nger-vehicle.

rates may apply. Text HELP for help

(whichever comes first) Wi-Fi trial.

• Connect up to ten Wi-Fi–equipped devices.

\*Compatible with select smartphone platforms. Foreflass.Connect <sup>TM</sup> endore regulard (see App Tarms for more information). Connected service and related feature functionality is subject to compatible ATS T-instructs detailability. Eaving technology/cellular retextors may direct functionality and availability, or continued provision of some features, publiciting them firms functioning. Message and data rates may apply/SEE you trucked Tow detable for our private policy.

The FordPass Connect™ modem is active and sending vehicle data (e.g., diagnostics) to Ford. See

in-vehicle Settings for connectivity options.



www.ford.com/help/privacy-terms/