
| VEH  | ICLE DESCRIPTION  |   | <sup>sк</sup> А55346  | California Air Resources Board   |
|--|---|---|---|--|
| ford.com   | 2025 350 HR CARGO RWD<br>148" WHEELBASE<br>3.5L ECOBOOST V6 (GAS)<br>10-SPEED TRANSMISSION  | EXTERIOR<br>OXFORD WHIT<br>INTERIOR<br>DARK PALAZZ  |   | Environmental  |
| STANDARD EQUIPMENT INCLUDED  | T NO EXTRA CHARGE   |   |   | These ratings are not directly comparable to the U   |
| EXTERIOR<br>• AUXILIARY FUEL PORT<br>• BODY SIDE MOLDINGS - BLACK<br>• BUMPERS - CARBON BLACK<br>• FULL SIZE SPARE TIRE/WHEEL<br>• HEADLAMP COURTESY DELAY<br>• WIPERS - RAIN-SENSING  | INTERIOR<br>• AIR CONDITIONING<br>• ASSIST HANDLES - A-PILLAR<br>• CENTER CONSOLE<br>• INTERIOR LIGHTING - LED<br>• LOCKING GLOVE BOX<br>• POWERPOINT - 12V (FRONT)<br>• STEERING - TILT/TELESCOPIC<br>• TACHOMETER | FUNCTIONAL<br>• AUTO HIGH-BEAM HEADLAMPS<br>• ELECTRONIC PWR ASST STEER<br>• FORWARD COLLISION WARNING<br>• HILL START ASSIST<br>• LANE-KEEPING SYSTEM<br>• POST-COLLISION BRAKING<br>• PRE-COLLISION BRAKING<br>• PRE-COLLISION ASSIST W/AEB<br>• REAR VIEW CAMERA<br>W/ TRAILER HITCH ASSIST<br>• SELECTABLE DRIVE MODES<br>• SIDE-WIND STABILIZATION | <ul> <li>SAFETY/SECURITY</li> <li>3 POINT SAFETY BELTS</li> <li>ADVANCETRAC™ WITH RSC®</li> <li>AIRBAGS ⊠ FRONT, SIDE AND<br/>SAFETY CANOPY® SYSTEM</li> <li>BRAKES - 4WHEEL DISC W/ABS</li> <li>SECURILOCK® ANTI-THEFT SYS</li> <li>SOS POST-CRASH ALERT SYS™</li> <li>TIRE PRESSURE MONIT SYS</li> <li>WARRANTY</li> <li>3YR/36,000 BUMPER / BUMPER</li> <li>5YR/60,000 POWERTRAIN</li> <li>5YR/60,000 ROADSIDE ASSIST</li> </ul> | For information on how to compare, plea<br>Protect the environment. Choose<br>Greenhouse Gas Rating (tailpipe only)<br>C-<br>A+<br>Cleaner   |
| INCLUDED ON THIS VEHICLE   | (MSRP)  | PRICE INFOR   | (MSRP)  | Vehicle emissions are a primary contributor to climate chang<br>California Air Resources Board based on this vehicle's meas  |
| PREFERRED EQUIPMENT PKG.101A<br>3.5L ECOBOOST V6 (GAS)<br>3.73 NON-LIMITED SLIP AXLE<br>REAR COMPARTMENT LIGHTING<br>FRONT LICENSE PLATE BRACKET<br>9500# GVWR PACKAGE<br>50 STATE EMISSIONS<br>REVERSE SENSING SYSTEM<br>HD TRAILER TOW PACKAGE<br>RADIO - SYNC3, 4" SCN<br>EXTENDED FUEL TANK (31 GAL)<br>FRONT OVERHEAD SHELF<br>2 ADDITIONAL KEYS<br>LOAD AREA PROTECTION PKG<br>.VINYL F/R FLOOR COVERING | 2,700.00<br>NO CHARGE<br>75.00<br>NO CHARGE<br>NO CHARGE<br>295.00<br>485.00<br>280.00<br>280.00  | TOTAL OPTIO<br>TOTAL VEHICI<br>DESTINATION  | LE & OPTIONS/OTHER 59,045.00  |  |
|  | 285.00<br>75.00<br>75.00<br>575.00  |   |   | Frontal<br>CrashDriver<br>Passenger $\star \star \star \star \star$ Based on the risk of injury in a frontal impact.<br>Should ONLY be compared to other vehicles of similar size and weight.  |
|  |   |   |   | SideFront seatNot RatedCrashRear seatNot RatedBased on the risk of injury in a side impact.  |
|  |   |   |   | Rollover       Not Rated         Based on the risk of rollover in a single-vehicle crash.         Star ratings range from 1 to 5 stars (★★★★), with 5 being         Source: National Highway Traffic Safety Administration (Normal Weaks)         www.safercar.gov or 1-888-327-4236                                 |
|  | CS15  | TOTAL   | MSRP \$61,140.00  | 1FTBW3XG8SKA55346  |
|  | RAMP TWO  | #:<br>21 100X O/T 2 Eord Credit   | Whether you decide to lease or finance your<br>vehicle, you'll find the choices that are right<br>for you. See your dealer for details or visit<br>www.ford.com/finance.  | WARNING: Operating, servicing and maintaining a passenger vehic vehicle can expose you to chemicals including engine exhaust, carb lead, which are known to the State of California to cause cancer and birth d  |
|  | This label is affixed pursuant to<br>Information Disclosure Act. G<br>State and Local taxes are not<br>options or accessories are not   | o the Federal Automobile<br>asoline, License, and Title Fees,<br>ncluded. Dealer installed SD042 N F  | RB 2X 525 001034 04 04 25   | Lead, which are known to the State of California to cause cancer and birth of<br>To minimize exposure, avoid breathing exhaust, do not idle the engine excor-<br>vehicle in a well-ventilated area and wear gloves or wash your hands freque<br>For more information go to www.P65Warnings.ca.gov/passenger-vehicle. |

1202504155173



www.ford.com/help/privacy-terms/