МІС-005819 со	9-NORMAL,NB,205819,SF162 873	7 320250622 6479	CERTCERTCERT TRD RAMPBUMPCA	MPBOOKEXFLROTABATT 8
r Ford ford.com	PEHICLE DESCRIPTION RANGER 2025 SUPERCREW 4X4 XL 128" WHEELBASE 2.3L ECOBOOST ENGINE 10-SPEED AUTO TRANSMISSION	INTERIOR	SL E28624 GRAY METALLIC SEATS	EPA DOT Fuel Economy and Er Fuel Economy Standard Fuel Economy Standard MPG MPG
STANDARD EQUIPMENT INCLUDE EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FULL SIZE SPARE TIRE/WHEEL • FULL Y BOXED STEEL FRAME • GRILLE - BLACK • HEADLAMPS - AUTO ON/OFF • PICKUP BOX TIE DOWN HOOKS • REMOTE TAILGATE LOCK • WHEEL LIP MOLDINGS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 100A • USERIES OPTIONAL EQUIPMENT/OTHER 255/70 R17 A/T TIRE 3.73 LOCKING RR DIFFERENTIAL STX APPEARANCE PACKAGE .FOG LAMPS .17" SILVER PAINTED ALUM WHL FRONT LICENSE PLATE BRACKET CARPET FLOORING RUNNING BOARDS - BLACK TRAILER TOW PACKAGE	ED AT NO EXTRA CHARGE NTERION 1-1-OUCH UP/DOWN DRIVER WIN 10° CENTER TOUCHSCREEN 2ND ROW FOLD BENCH 0 DIGITAL INSTRUMENT CLUSTER 10CKING GLOVE BOX 10CKING GLOVE BOX 10CWERPOINTS-12V, USB 10CKING SCOPE STR COLUMN (MSRP) 420.00 NO CHARGE 145.00 750.00 535.00	EUNCTIONAL AUDIO - 6 SPEAKERS BRAKES - ANTI-LOCK SYSTEM IELECTRIC PARKING BRAKE INDEPENDENT FRONT SUSPEN PRE-COLLISION ASSIST W/AEB REAR VIEW CAMERA IELECTSHIFT® SYNC®4A PREC INCOM DATE SPRICE TOTAL OPTION TOTAL VEHICL DESTINATION	\$36,830.00 IS/OTHER 1,850.00 E & OPTIONS/OTHER 38,680.00	fueleconomy.gov Calculate personalized estimates and compare vehicles
	RAMP ONE RY08 RAMP TWO		e QR Code to	Source: National Highway Traffic Safety Adm www.safercar.gov or 1-888-327 1FTER4PH6SLE28624
	This label is affixed pursuant to the Information Disclosure Act. Gasolin State and Local taxes are not includ options or accessories are not includ	6-8166 O/T 2 Federal Automobile ne, License, and Title Fees, ded. Dealer installed SF162 N R	e details about icle B 2X 530 005819 06 16 25	WARNING: Operating, servicing and maintaining a p vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash yo For more information go to www.P65Warnings.ca.gov/passe

