
MIC-006962 AZ	9-NORMAL, NB, 106962, SF021 952	0 320250610 6329			PBOOKEXFLROTABATT	1785/
	2025 SUPERCREW 4X4 XL 128" WHEELBASE 2.3L ECOBOOST ENGINE 10-SPEED AUTO TRANSMISSION	EXTERIOR OXFORD W INTERIOR BONY CL	SL E305 THITE OTH SEATS	567	EPA DOT Fuel Economy Fuel Economy	
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FENDER BADGE • FULL SIZE SPARE TIRE/WHEEL • FULLY BOXED STEEL FRAME • GRILLE - BLACK • HEADLAMPS - AUTO ON/OFF • PICKUP BOX TIE DOWN HOOKS • REMOTE TAILGATE LOCK • WHEEL LIP MOLDINGS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 100A • XL SERIES OPTIONAL EQUIPMENT/OTHER 255/70 R17 A/T TIRE 3.73 LOCKING RR DIFFERENTIAL 4X4 REGIONAL DISCOUNT PKG STX APPEARANCE PACKAGE .FOG LAMPS .17" SILVER PAINTED ALUM WHL CARPET FLOORING TRAILER TOW PACKAGE		FUNCTIONAL • AUDIO - 6 SPEAKERS • BRAKES - ANTI-LOCK SYSTEM • ELECTRIC PARKING BRAKE • INDEPENDENT FRONT SUSPEN • PRE-COLLISION ASSIST W/AEB • REAR VIEW CAMERA • REMOTE KEYLESS ENTRY • SELECTSHIFT® • SYNC®4A PRICE IN BASE PRI TOTAL OF TOTAL VE DESTINAT	OCK SYSTEM NG BRAKE• BELT-MINDER CHIME • CTR HIGH MOUNT STOP LAMP • LATCH CHILD SAFETY SYSTEM • PASSIVE ANTI-THEFT SYSTEM • TIRE PRESSURE MONIT SYS		4 4 19 26 combined city/hwy city highway 4.5 gallons per 100 miles Annual fuel Cost \$22,4000 5 \$22,4000 6 \$22,4000 6 \$32,500 Fuel Economy 8 \$4,500 1 \$4,500 1 \$52,4000 1 1 1	
	RAMP ONE RP1P RAMP TWO		AL MSRP \$39,3 The QR Code to	375.00	Based on the risk of injury in a frontal in Should ONLY be compared to other vel Side Front seat Crash Rear seat Based on the risk of injury in a side imp Rollover Based on the risk of rollover in a single- Star ratings range from 1 to 5 stars Source: National Highway Trate www.safercar.get	mpact. hicles of similar size ar $\star \star \star$ bact. -vehicle crash. S ($\star \star \star \star$), wit
	ITEM #:	1-1410 O/T 2 E Federal Automobile ine, License, and Title Fees, ded. Dealer installed SF021	ore details about vehicle N RB 2X 530 006962 06 0	2 25	WARNING: Operating, servicing a vehicle can expose you to chemica lead, which are known to the State of Cal To minimize exposure, avoid breathing exposure, avoid breathing exposure in a well-ventilated area and wear For more information go to www.P65Ward	als including engine ex lifornia to cause cancel xhaust, do not idle the r gloves or wash your h



##