FD

ford.com	LE DESCRIPTION -150 2024 F-150 4X2 SUPERC 145" WHEELBASE 5.0L V8 ENGINE ELEC TEN-SPEED AUTO		RK ERIOR DXFORD WHITE ERIOR BLACK STX CLOTH 40/CG	<b>524438</b>	EPA DOT Fuel Economy   Fuel Economy   Fuel Economy   MPG
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • DAYTIME RUNNING LAMPS • ASY FUEL® CAPLESS FILLER • FOG LAMPS-LED • FULLY BOXED STEEL FRAME • GRILLE - BLACK & DARK GRAY • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTO LAMP (NOVOFF) • LED REFLECTOR HEADLAMPS • PICKUP BOX TIE DOWN HOOKS • POWER TAILGATE LOCK • REAR PRIVACY GLASS • TRAILER SWAY CONTROL • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 200A • STX SERIES OTOARK GRAY W/MACH ALUM WHL EXTENDED RANGE 36GAL FUEL TAN 5.0. V8 ENGINE 275/60R20 BSW ALL-SEASON 3.15 RATIO REGULAR AXLE 6850# GVWR PACKAGE FRONT LICENSE PLATE BRACKET 50 STATE EMISSIONS	INTERIOR • 12" PRODUCTIVITY SCREEN • CRUISE CONTROL • DOOR LOCKS - POWER • DUAL SUNVISORS • ILLUMINATED ENTRY • MESSAGE CTR: OUTSIDE TEMI COMPASS, TRIP COMPUTER • POWERPOINTS - 12V • TILT/TELESCOPE STR COLUMN (MSRP) 1,660.00 NO CHARGE NO CHARGE NO CHARGE	HOTSPOT TELEMAT • HILL START ASSIST	ADVANG ADVANG AIRBAG MOUNT AIRBAG MOUNT CONNECTOR AIRBAG CTR HIG SOS PC STOLEN TIEM RAKING SIST W/AEB AND AIRBAG CTR HIG SOS PC STOLEN	0000 BUMPER / BUMPER 0000 POWERTRAIN 0000 ROADSIDE ASSIST 0,000 HYBRID BATTERY (MSRP) \$48,435.00 1,660.00 S/OTHER 50,095.00 1,995.00	Image: A figster in the second sec
	RAMP ONE CG7Z	CONVOY	TOTAL MSRP	\$50,090.00 decide to lease or finance your	1FTEW2K54RKF24438
	RAMP TWO CONVOY   ITEM #: 21-4668 O/T 2   This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		vehicle, you'll find the choices that are right Ford Credit for you. See your dealer for details or visit www.ford.com/finance. RK212 N RB 2X 470 003720 10 21 24		WARNING: Operating, servicing and maintaining a pa vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle th vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passer



2202410294853