FD

Ford.com	ICLE DESCRIPTION F-150 2024 F-150 4X2 SUPERCI 145" WHEELBASE 5.0L V8 ENGINE ELEC TEN-SPEED AUTO	C INTE	RF ERIOR DXFORD WHITE ERIOR BLACK STX CLOTH 40/C	A88073	EPA DOT Fuel Economy and En Fuel Economy MPG MPGe.
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FOG LAMPS-LED • FULLY BOXED STEEL FRAME • GRILLE - BLACK & DARK GRAY • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTO LAMP (ON/OFF) • LED REFLECTOR HEADLAMPS • DOWER TAILGATE LOCK • REAR PRIVACY GLASS • TRAILER SWAY CONTROL • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 200A • STX SERIES OPTIONAL EQUIPMENT/OTHEN .20° DARK GRAY W/MACH ALUM WHL .EXTENDED RANGE 36GAL FUEL TAN 5.0L V8 ENGINE .275/60R20 BSW ALL-SEASON 3.15 RATIO REGULAR AXLE 6850# GWWR PACKAGE FRONT LICENSE PLATE BRACKET 50 STATE EMISSIONS MOBILE OFFICE PACKAGE	AL NO EXTRA CHARGE INTERIOR • 12" PRODUCTIVITY SCREEN • CRUISE CONTROL • DUAL SUNVISORS • ILLUMINATED ENTRY • MESSAGE CTR: OUTSIDE TEMP COMPASS, TRIP COMPUTER • POWERPOINTS - 12W • TILT/TELESCOPE STR COLUMN (MSRP) 1,570.00 NO CHARGE NO CHARGE 535.00	HOTSPOT TELEMAT • HILL START ASSIST	• ADVAN FFIC ALERT • AIRBA HITCH W/ • AIRBA CONNECTOR • AIRBA ECT 5GWI-FI • PERIM ICS MODEM • SOS P TEM • TIRE P RAKING • SIST W/AEB AND • 3YR/36 • SYR/60 • SYR/60	0,000 BUMPER / BUMPER 0,000 POWERTRAIN 0,000 ROADSIDE ASSIST 00,000 HYBRID BATTERY (MSRP) \$48,230.00 2,105.00 NS/OTHER 50,335.00 Y 1,995.00	initial initinitial initinitial initinitial initinitial initial initial initial
	RAMP ONE RA84 RAMP TWO	RAIL	Find vehicle, you'l	u decide to lease or finance your Il find the choices that are right	1FTEW2K5XRFA88073
	72-3134 O/T 2 This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		Ford Credit for you. See your dealer for details or visit www.ford.com/finance.		lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle th vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passer



2202404302488