	CLE DESCRIPTION		^{RK} F10	760	FPA
ford.com	F-150 2024 F-150 4X2 SUPERCREW 145" WHEELBASE 2.7L V6 ECOBOOST ELEC TEN-SPEED AUTO TRANS	INTERIOR	NET TINTED CC CLOTH 40/CON/40	700	EPA DOT Fuel Economy and Environment Fuel Economy MPG Standard Pic 73 MPG. Th MPGe.
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FOG LAMPS-LED • FULLY BOXED STEEL FRAME • GRILLE - BLACK & DARK GRAY • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LED REFLECTOR HEADLAMPS • PICKUP BOX TIE DOWN HOOKS • POWER TAILGATE LOCK • REAR PRIVACY GLASS • TRAILER SWAY CONTROL • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 200A • STX SERIES OPTIONAL EQUIPMENT/OTHER 2024 MODEL YEAR RAPID RED MET TINTED CC .EXTENDED RANGE 36GAL FUEL TAN .275/60R20 BSW ALL-SEASON 3.55 ELECTRONIC LOCK RR AXLE 6426# GVWR PACKAGE FRONT LICENSE PLATE BRACKET STX BLACK APPEARANCE PACKAGE .20" GLOSS BLACK WHEELS 50 STATE EMISSIONS	TIND EXTRA CHARGE INTERIOR 12" PRODUCTIVITY SCREEN CRUISE CONTROL DOOR LOCKS - POWER DUAL SUNVISORS ILLUMINATED ENTRY MESSAGE CTR: OUTSIDE TEMP, COMPASS, TRIP COMPUTER POWERPOINTS - 12V TILT/TELESCOPE STR COLUMN (MSRP) 495.00 470.00 NO CHARGE 1,585.00 NO CHARGE	TOTAL VEHI DESTINATIO	CLE & OPTIONS/OTHER	EAT ACT CANOPY® TOP LAMP LERT SYS™ 1 YR PLAN NIT SYS 8 / BUMPER TRAIN DE ASSIST	Image: And the second secon
	RAMP ONE CATB RAMP TWO ITEM #:	CONVOY	MSRP \$50,8 Whether you decide to lease vehicle, you'll find the choic	es that are right	1FTEW2KP3RKF10760

Ford Credit for you. See your dealer for details or visit

www.ford.com/finance.

RJ122 N RB 2X 455 004357 09 12 24

This label is affixed pursuant to the Federal Automobile

State and Local taxes are not included. Dealer installed

Information Disclosure Act. Gasoline, License, and Title Fees,

options or accessories are not included unless listed above.

52-S504 O/T 2

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl lead, which are known to the State of California to cause cancer and birth defects or other reproducuve narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

2202409212647

