Ford.com	<b>-150</b> 2025 F-150 4X4 SUPER CAB 145" WHEELBASE 2.7L V6 ECOBOOST ELEC TEN-SPEED AUTO TRANS	INTERI	FORD WHITE	998	EPA DOT Fuel Econor Fuel Economy	my and En PG Standard Pi 87 MPG. TH MPGe.
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LED REFLECTOR HEADLAMPS • LOCKING REMOVABLE TAILGATE • MANUAL FOLD POWER MIRRORS • PICKUP BOX TIE DOWN HOOKS • POWER TAILGATE LOCK • TRAILER SWAY CONTROL • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 101A • JUST STEEL WHEELS · 265/70R 17 BSW ALL-TERRAIN · 3.55 RATIO REGULAR AXLE 6550# GVWR PACKAGE FRONT LICENSE PLATE BRACKET 50 STATE EMISSIONS EXTENDED RANGE 36GAL FUEL TANK	NO EXTRA CHARGE POUSE CONTROL POUSE CONTROL POUSE CONTROL POUSE CONSUME POUSE CONSUME POUSE CTR: OUTSIDE TEMP, COMPASS, TRIP COMPUTER TILT/TELESCOPE STR COLUMN (MSRP) NO CHARGE NO CHARGE		TCH W/       • AIRBAGS - SAFETY CANOPY®         • CTR HIGH MOUNT STOP LAMP         • PERIMETER ALARM         • SECURE PKG 1 YR INCLUDED         • SOS POST-CRASH ALERT SYS™         • TIRE PRESSURE MONIT SYS         AKING         ST W/AEB         ND         • SYR/60,000 BUMPER / BUMPER         • SYR/60,000 ROADSIDE ASSIST		<b>fueleconomy.gov</b> Calculate personalized estimates and compare vehicles	
	RAMP ONE CK8P			555.00	Side CrashFront sea Rear seaBased on the risk of injury in a side iRolloverBased on the risk of rollover in a singStar ratings range from 1 to 5 st Source: National Highway T www.saferca	at $\star \star$ It $\star \star$ mpact. gle-vehicle crash. ars ( $\star \star \star \star$ ), with the second seco
	This label is affixed pursuant to the Information Disclosure Act. Gasol	17-K257 O/T 2 e Federal Automobile	Scan The QR Code to get more details about this vehicle		WARNING: Operating, servicing vehicle can expose you to chen lead, which are known to the State of of To minimize exposure, avoid breathing vehicle in a well-ventilated area and w For more information go to www.P65W	California to cause canc exhaust, do not idle the

