FD

9-NORMAL, NB, 106020, RL121 9526

220241120 **0927**

U | W | MI | C | ULC CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

ford.com	F-150 2025 F-150 4X4 SUPERCREW 157" WHEELBASE 3.5L POWERBOOST FULL HYE HYBRID ELEC 10-SPD AUTO 1	MAR BRID INTERIO	IOR RSH GRAY	09795	EPA DOT Fuel Economy and En Fuel Economy MPG Standard 84 MPG. MPGe.
EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LED REFLECTOR HEADLAMPS • PICKUP BOX TIE DOWN HOOKS • POWER TAILGATE LOCK • REAR PRIVACY GLASS • TRAILER SWAY CONTROL • WIPERS- INTERMITTENT • ZONE LIGHTING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 301A • XLT SERIES • 8-WAY POWER DRIVERS SEAT • DUAL ZONE AUTO TEMP CONTROL COPTIONAL EQUIPMENT/OTHER LED FOG LAMPS 3.5L POWERBOOST FULL HYBRID HYBRID ELEC 10-SPD AUTO TRANS 275/65R 18 BSW ALL-TERRAIN 3.73 ELECTRONIC LOCK RR AXLE 7400# GVWR PACKAGE 6" BRIGHT ANODIZED STEP BAR 50 STATE EMISSIONS MOBILE OFFICE PACKAGE 18" CHROME-LIKE PVD WHEELS STANDARD FUEL TANK BED UTILITY PACKAGE .TAILGATE STEP AND WORK SURFAC	INTERIOR 12" PRODUCTIVITY SCREEN DOOR LOCKS - POWER DUAL SUNVISORS ILLUMINATED ENTRY MESSAGE CTR: OUTSIDE TEMP, COMPASS, TRIP COMPUTER TILT/TELESCOPE STR COLUMN (MSRP) 1,585.00 1,900.00 NO CHARGE NO CHARGE 1,045.00 635.00		C ALERT H W/ NECTOR SGWI-FI MODEM MODEM SECURE PI SOS POST- W/AEB T MAEB MODES SYR/60,000 CREEN AIRBAGS - AIRBAGS - CTR HIGH I SCURE PI SOS POST- SYR/36,000 SYR/60,000	Imac™ WITH RSC® FRONT SEAT SIDE IMPACT SAFETY CANOPY® MOUNT STOP LAMP R ALARM KG 1 YR INCLUDED -CRASH ALERT SYS™ SURE MONIT SYS D BUMPER / BUMPER POWERTRAIN D ROADSIDE ASSIST D0 HYBRID BATTERY (MSRP) \$53,895.00 5,165.00 THER 59,060.00 1,995.00 MTS	Image: Angle Angl
	RAMP ONE CM59 RAMP TWO	CONVOY		\$59,155.00 ide to lease or finance your the choices that are right dealer for details or visit nance	IFTFW3LD8SFA09795
	This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not in options or accessories are not	o the Federal Automobile Isoline, License, and Title Fees, Icluded. Dealer installed	RL121 N RB 2X 530 00		lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle th vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passer



2202411200927