9-NORMAL, NB, 103372, SD021 9830

220250411 **1400**

U W AZ ULC CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

Ford.com	F-150 2025 F-150 4X4 SUPERCREW 145" WHEELBASE 3.5L POWERBOOST FULL HYB HYBRID ELEC 10-SPD AUTO T	RID INTERIO	DR SE WHITE METALLIC	4128	EPA DOT Fuel Economy and En Fuel Economy R 2 2 MPG Standard 87 MPG. MPGe.
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DAYTIME RUNNING LAMPS • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LED PROJECTOR W/ DYNAMIC BENDING HEADLAMPS • LED SIDE-MIRROR SPOTLIGHTS • LED TAIL LAMPS • POWER MIRRORS • REMOTE TAILGATE RELEASE • TRAILER SWAY CONTROL INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 502A • LARIAT SERIES • B&O UNLEASHED SOUND SYS 14SPK • MOBILE OFFICE PACKAGE • WIRELESS CHARGING PAD OPTIONAL EQUIPMENT/OTHER 3.5L POWERBOOST FULL HYBRID HYBRID ELEC 10-SPD AUTO TRANS 275/60R20 BSW ALL-TERRAIN 3.73 ELECTRONIC LOCK RR AXLE 7400# GYWR PACKAGE LARIAT BLACK APPEARANCE PKG 2.0" GLOSS BLACK PAINTED ALUM 50 STATE EMISSIONS PRO POWER ONBOARD - 7.2KW BLUECRUISE EQUIP: 90DAY TRIAL TOW/HAUL PACKAGE .INTEGRATED TRAILER BRAKE CONT FX4 OFF-ROAD PACKAGE .PRO ACCESS TAILGATE	AT NO EXTRA CHARGE	BA TO DE TC LA PC	5GWI-FI MOUNTED SIDE MODEM • AIRBAGS - SAFE /PUSH • CTR HIGH MOUN • SECURE PKG 1 1 • SECURILOCK® A • SOS POST-CRAS W/AEB • TIRE PRESSURE • • • • • • • • • • • • • • • • • • •	™ WITH RSC® NT SEAT IMPACT ETY CANOPY® NT STOP LAMP YR INCLUDED ANTI-THEFT SYS SH ALERT SYS MPER / BUMPER VERTRAIN NDSIDE ASSIST BRID BATTERY (MSRP) \$63,360.00 14,715.00	Image: A grade of the second secon
	RAMP ONE RA1P RAMP TWO ITEM #	RAIL	Whether you decide to vehicle, you'll find the c	choices that are right r for details or visit	1FTFW5LD4SFA94128 WARNING: Operating, servicing and maintaining a province of the state of California to cause care
	This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not in options or accessories are not	the Federal Automobile soline, License, and Title Fees, cluded. Dealer installed	SD021 N RB 2X 555 003372	2.	lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passe



2202504111400