FD

9-NORMAL, NB, 300989, SD303 7764

W TX 220250509 6256 CERTCERT TRD RAMPBUMPCAMPBOOKEXFLROTABATT

145" W 3.5L PC		lı D INTE	ERIOR CONIC SILVER ERIOR SMOKED TRUFF	METALLIC	5797	EPA DOT Fuel Economy and En Fuel Economy R 2 2 MPG Standard P 87 MPG. T MPGe.
FULLY BOXED STEEL FRAME HEADLAMPS - AUTO HIGH BEAM HEADLAMPS - AUTOLAMP (ON/OFF) LED PROJECTOR W/ DYNAMIC BENDING HEADLAMPS LED SIDE-MIRROR SPOTLIGHTS LED TAIL LAMPS PWR FRT F PWR FRT F PWR FRT F AUTOLAMP A/C W/DU AACTIVEX S AUTO DIM ALTO DIM HTD PREM HTD/VENT	WR DRV & MULTI-ADJ PASS UCTIVITY SCREEN AL CLIMATE CONTROL SEATING MATERIAL CRUISE CONTROL REARVIEW MIRROR A WRAPPED STR WHL ILATED FRT SEATS PER/PASS LUMBAR	EUNCTIONAL • 360-DEGREE CAMEI • BLIS W/CROSS-TRA • FORDPASS™ CONN HOTSPOT TELEMAT • INTELLIGENT ACCES BUTTON START • LANE-KEEPING SYS • POST-COLLISION BS • PRE-COLLISION ASS • REVERSE BRAKE AS • REVERSE BRAKE AS • REVERSE SENSING REAR VIEW CAMERA • SIRIUSXM® W/360L • SYNC®4 W/EVR & 1	AFFIC ALERT IECT 5GWI-FI ICS MODEM SS W/PUSH TTEM RAKING SIST W/AEB STEM SSIST AND A - NA AK&HI 2" SCREEN PRICE INFORM BASE PRICE TOTAL OPTION: TOTAL VEHICLE DESTINATION 8 TOTAL BEFO	S/OTHER E & OPTIONS/OTHER DELIVERY ORE DISCOUNTS ST HYBRID DISC	™ WITH RSC® NT SEAT IMPACT ETY CANOPY® NT STOP LAMP YR INCLUDED ANTI-THEFT SYS SH ALERT SYS™ E MONIT SYS MPER / BUMPER VERTRAIN ADSIDE ASSIST BRID BATTERY (MSRP) \$63,360.00 7,385.00	Image: State of the second state s
20" CHROME-LIKE PVD WHEELS STANDARD FUEL TANK	RAMP ONE RH80 RAMP TWO	RAIL	TOTAL I	hether you decide to	'0,840.00	Based on the risk of injury in a side impact. Rollover ★ ★ Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★ ★ ★ ★ ★), w Source: National Highway Traffic Safety Admin www.safercar.gov or 1-888-327-4 1FTFW5LD6SFB25797
	ITEM #:	e, License, and Title Fees, ed. Dealer installed	Ford Credit fo	hicle, you'll find the c r you. See your dealer ww.ford.com/finance B 2X 560 000989	e <u>.</u>	WARNING: Operating, servicing and maintaining a pase vehicle can expose you to chemicals including engine end lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng



2202505096256