	DESCRIPTION RONCO SPC 2025 BIG BEND 4X4 5-PASSENGER 1.5L ECOBOOST ENGINE 8-SPD AUTO TRANSMISSION	EXTERIOR VELOC INTERIOR	SR E47S	936	EPA DOT Fuel Economy and En Fuel Economy IPA 7 MPG Small SU The best
ACTIVE GRILLE SHUTTERS     DOOR HANDLES - BLACK     EASY FUEL® CAPLESS FILLER     HEADLAMPS - AUTO HIGH BEAM     HEADLAMPS-LED     LIFTGATE W/ LIFTGLASS     MIRRORS - HTD/POWER GLASS     PRV GLS-2ND RW/LIFTGATE     REAR INT WIPER/WASH/DFRST     ROOF-RACK SIDE RAILS-BLACK     TAILLAMPS-LED	EXTRA CHARGE NTERION 1-TOUCH DOWN DRIVER WINDOW 60/40 SPLIT FOLD REAR SEAT DIGITAL INSTRUMENT CLUSTER DUAL ILLUM VIS VANITY MIRR ELECTRONIC AUTO TEMP CTRL FLOOD LIGHT ADJ LIFTGATE ILLUMINATED ENTRY SYSTEM MANUAL PASS SEAT - 4-WAY POWERPOINTS - 12V SMART CHARGING USB PORTS STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS 395.00 2,570.00	BASE TOTA TOTA DEST TOT BLA	<ul> <li>AIRBAG - DRIVER KNE</li> <li>AIRBAGS - DUAL STAC</li> <li>AIRBAGS - SAFETY C/</li> <li>FRT-PASS SENSING S</li> <li>INDIV TIRE PRESS MC</li> <li>LATCH CHILD SAFETY</li> <li>PERIMETER ALARM</li> <li>SECURILOCK® ANTI-T</li> <li>HI SIDE AIRBAGS</li> <li>SOS POST-CRASH AL</li> <li>SYR/36,000 BUMPER /</li> <li>SYR/60,000 POWERTF</li> <li>SYR/60,000 ROADSIDE</li> </ul>	E GE FRONT ANOPY® YSTEM INIT SYS YSTEM THEFT SYS ERT SYS™ BUMPER AIN E ASSIST (MSRP) \$29,995.00 2,965.00 32,960.00 1,595.00 32,960.00 1,595.00 - 750.00 - 750.00 - 750.00 - 750.00	Image: Additional and the second s
	RAMP ONE       RA4F         RAMP TWO       ITEM #:         This label is affixed pursuant to the Information Disclosure Act. Gasoli State and Local taxes are not inclus options or accessories are not inclused options	RAIL 1-146C O/T 2 Federal Automobile ne, License, and Title Fees, ded. Dealer installed	more information. TAL MSRP \$33,8 Whether you decide to lease vehicle, you'll find the choice: Credit for you. See your dealer for de www.ford.com/finance.	s that are right etails or visit	WARNING: Operating, servicing and maintaining a particular vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause car To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passe

