| HRM-004191 <sub>NJ</sub>  | 9-NORMAL, NB, 004191, SF052 <b>175</b>   | 54   | CERTCERTCERT TRD RAMPBUMPCAM                                       | DEBOOKEXFLROTABATT 02705  |
|---|--|--|--|---|
|   | CLE DESCRIPTION<br><b>VAVERICK</b><br>2025 XL FWD<br>121" WHEELBASE<br>2.5L HYBRID ENGINE<br>POWER-SPLIT ELECTRIC CVT  | EXTERIOR<br>OXFORD WH<br>INTERIOR<br>BLACK ONY)  | SR <b>B08085</b><br>Ite<br>K-MED DK SLATE TRI                      | EPA<br>DOT Fuel Economy and En<br>Fuel Economy<br>MPG. The b  |
| STANDARD EQUIPMENT INCLUDED AT<br>EXTERIOR<br>• CARGO BOX TIE DOWN HOOKS<br>• DAYTIME RUNNING LAMPS<br>• DOOR HANDLES - BLACK<br>• EASY FUEL® CAPLESS FILLER<br>• FLEXBEDT <sup>M</sup> STORAGE SYSTEM<br>• GRILLE - BLACK MESH<br>• HEADLAMPS-LED AUTO ON/OFF<br>• LED REFLECTOR HEADLAMPS<br>• MANUAL LOCKING TAILGATE<br>• WIPERS- INTERMITTENT<br>INCLUDED ON THIS VEHICLE<br>EQUIPMENT GROUP 100A<br>OPTIONAL EQUIPMENT/OTHER<br>2K TRAILER HITCH RECEIVER<br>FLR LNRS WITHOUT CARPETED MATS<br>BEDLINER - SPRAY-IN<br>50 STATE EMISSIONS<br>FRONT LICENSE PLATE BRACKET | INTERIOR<br>• 1-TOUCH DOWN DRIVER WINDOW<br>• 2ND ROW BENCH FLIP-UP W/<br>UNDER-SEAT STORAGE<br>• 8.0° PRODUCTIVITY SCREEN<br>• COTH BENCH REAR SEAT<br>• CRUISE CONTROL<br>• DUAL USB<br>• MANUAL A/C, SINGLE ZONE<br>• POWER LOCKS AND WINDOWS<br>• POWER LOCKS AND WINDOWS<br>• POWER POINTS - 12V<br>• ROTARY GEAR SHIFT DIAL<br>• TILT/TELESCOPE STR COLUMN<br>• VINYL SOFT CONSOLE LID<br>(MSRP) | TOTAL VEHI   |  | <ul> <li>Soo Age and a start of the sta</li></ul> |
|   | RAMP ONE<br>RU41<br>RAMP TWO   | RAIL Scan T  | - MSRP \$30,570.00<br>The QR Code to<br>pre details about<br>hicle | Source: National Highway Traffic Safety Admin<br>www.safercar.gov or 1-888-327-4<br>3FTTW8A35SRB08085<br>WARNING: Operating, servicing and maintaining a pas<br>vehicle can expose you to chemicals including engine of<br>lead, which are known to the State of California to cause canc   |
|   | This label is affixed pursuant to th<br>Information Disclosure Act. Gasol<br>State and Local taxes are not inclu<br>options or accessories are not inc   | e Federal Automobile<br>line, License, and Title Fees,<br>uded. Dealer installed SF052 N | RB 2X 560 004191 06 05 25  | lead, which are known to the State of California to cause cance<br>To minimize exposure, avoid breathing exhaust, do not idle the<br>vehicle in a well-ventilated area and wear gloves or wash your<br>For more information go to www.P65Warnings.ca.gov/passeng  |

