HRM-001776 CA 9-NORMAL, NB, 201776, SE072 11656			UTC U W CA C CERTCERTCERT TRD RAMPBUMPCAMPBOOKEXFLROTABATT 750	
Ford.com	ICLE DESCRIPTION MAVERICK 2025 XL FWD 121" WHEELBASE 2.5L HYBRID ENGINE POWER-SPLIT ELECTRIC CVT	EXTERIOR OXFORD V INTERIOR BLACK ON	SR A93001 WHITE NYX-MED DK SLATE TRI	EPA DOT Fuel Economy and En Fuel Economy IN 2 2 MPG Small Pick MPG. The
STANDARD EQUIPMENT INCLUDED A EXTERIOR • CARGO BOX TIE DOWN HOOKS • DAYTIME RUNNING LAMPS • DOOR HANDLES - BLACK • EASY FUEL® CAPLESS FILLER • FLEXBED™ STORAGE SYSTEM • GRILLE - BLACK MESH • HEADLAMPS-LED AUTO HI-BEAM • HEADLAMPS-LED AUTO ON/OFF • LED REFLECTOR HEADLAMPS • MANUAL LOCKING TAILGATE • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 100A OPTIONAL EQUIPMENT/OTHER FORD CO-PILOT360® 1.0 .REAR PARKING SENSORS 50 STATE EMISSIONS FRONT LICENSE PLATE BRACKET	AT NO EXTRA CHARGE INTERIOR 1-TOUCH DOWN DRIVER WINDOW 2 ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE 8.0" PRODUCTIVITY SCREEN (LOTH BENCH REAR SEAT CRUISE CONTROL 1044 USB MANUAL A/C, SINGLE ZONE POWER LOCKS AND WINDOWS POWER LOCKS AND WINDOWS POWERPOINTS - 12V ROTARY GEAR SHIFT DIAL 11T/TELESCOPE STR COLUMN VINYL SOFT CONSOLE LID 195.00 NO CHARGE NO CHARGE	BASE PF TOTAL O TOTAL V	• BELT-MINDER CHIME • LATCH CHILD SAFETY SYSTEM • SECURILOCK® ANTI-THEFT SYS • TIRE PRESSURE MONIT SYS • TIRE PRESSURE MONIT SYS • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN • 5YR/60,000 POWERTRAIN • 5YR/60,000 HYBRID UNIQUE • COMPONENTS IF EQUIPPED	100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100
	RAMP ONE RA84 RAMP TWO	RAIL	edit for you. See your dealer for details or visi	Dur
	This label is affixed pursuant to th Information Disclosure Act. Gaso State and Local taxes are not inclu options or accessories are not in	ne Federal Automobile Iline, License, and Title Fees, uded. Dealer installed SE072	2 N RB 2X 560 001776 05 07 25	lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passed

