HRM-002142 <sub>FL</sub>	9-NORMAL,NB,102142,SC111 <b>317</b>	70	UTC     U     W     FL       CERT     CERT     TRD     RAMP     BUMP	CAMPBOOKEXFLROTA 00
	ICLE DESCRIPTION MAVERICK 2025 XL FWD 121" WHEELBASE 2.5L HYBRID ENGINE POWER-SPLIT ELECTRIC CVT	INTERIOR	SR <b>A57889</b> Red gray metallic hyx-med dk slate tri	EPA DOT Fuel Economy and Env Fuel Economy MPG. The b
STANDARD EQUIPMENT INCLUDED A EXTERIOR • CARGO BOX TIE DOWN HOOKS • DAYTIME RUNNING LAMPS • DOOR HANDLES - BLACK • EASY FUEL® CAPLESS FILLER • FLEXBED™ STORAGE SYSTEM • GRILLE - BLACK MESH • HEADLAMPS-LED AUTO ON/OFF • LED REFLECTOR HEADLAMPS • MANUAL LOCKING TAILGATE • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 100A OPTIONAL EQUIPMENT/OTHER 2K TRAILER HITCH RECEIVER 50 STATE EMISSIONS DEALER INSTALLED OPTIONS First Aid Kit SecuriCodeÖ Keyless-Entry Keyp	INTERIOR • 1-TOUCH DOWN DRIVER WINDOW • 2ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE • 8.0" PRODUCTIVITY SCREEN • CLOTH BENCH REAR SEAT • CRUISE CONTROL • DUAL USB • MANUAL A/C, SINGLE ZONE • POWER LOCKS AND WINDOWS • POWERPOINTS - 12V • ROTARY GEAR SHIFT DIAL • TILT/TELESCOPE STR COLUMN • VINYL SOFT CONSOLE LID (MSRP)	BASE PR TOTAL O TOTAL VI	• BELT-MINDER CHIME • LATCH CHILD SAFETY SYSTEM • SECURILOCK® ANTI-THEFT SYS • TIRE PRESSURE MONIT SYS • TIRE PRESSURE MONIT SYS • 3YR/36,000 BUMPER / BUMPER • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN • 5YR/60,000 POWERTRAIN • 5YR/60,000 HYBRID UNIQUE • COMPONENTS IF EQUIPPED	fueleconomy.gov Calculate personalized estimates and compare vehicles
	RAMP ONE RH12 RAMP TWO ITEM #:	RAIL	AL MSRP \$28,975.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	3FTTW8A38SRA57889
	This label is affixed pursuant to the Information Disclosure Act. Gase State and Local taxes are not incl options or accessories are not in	oline, License, and Title Fees, luded. Dealer installed SC111	N RB 2X 550 002142 03 11 25	To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

