HRM-001122 _{FL}	9-NORMAL, NB, 201122, SC102 996	50	UTC U W FL CERT CERT TRD RAMP BUMP	CAMPBOOKEXFLROTA 0 803
	ICLE DESCRIPTION MAVERICK 2025 XL FWD 121" WHEELBASE 2.5L HYBRID ENGINE POWER-SPLIT ELECTRIC CVT	EXTERIOR OXFORD WH INTERIOR BLACK ONY	SR A60969 IITE x-med dk slate tri	Fuel Economy and Env Fuel Economy MPG. The b
STANDARD EQUIPMENT INCLUDED A EXTERIOR • CARGO BOX TIE DOWN HOOKS • DAYTIME RUNNING LAMPS • DOOR HANDLES - BLACK • EASY FUEL® CAPLESS FILLER • FLEXBED™ STORAGE SYSTEM • GRILLE - BLACK MESH • HEADLAMPS-LED AUTO HI-BEAM • HEADLAMPS-LED AUTO ON/OFF • LED REFLECTOR HEADLAMPS • MANUAL LOCKING TAILGATE • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 100A OPTIONAL EQUIPMENT/OTHER 2K TRAILER HITCH RECEIVER 50 STATE EMISSIONS DEALER INSTALLED OPTIONS First Aid Kit SecuriCodeÖ Keyless-Entry Keyp	INTERIOR 1-TOUCH DOWN DRIVER WINDOW 2ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE 8.0" PRODUCTIVITY SCREEN COUTH BENCH REAR SEAT CRUISE CONTROL 0UAL USB MANUAL A/C, SINGLE ZONE POWER LOCKS AND WINDOWS POWER LOCKS AND WINDOWS POWERPOINTS - 12V ROTARY GEAR SHIFT DIAL TILT/TELESCOPE STR COLUMN VINYL SOFT CONSOLE LID MSRP	BASE PRIC TOTAL OPT TOTAL VEH	SAFETY/SECURITY ARBAGS - SAFETY CANOPY® BELT-MINDER CHIME ATCH CHILD SAFETY SYSTEM SECURILOCK® ANTI-THEFT SYS TIRE PRESSURE MONIT SYS BYR/60,000 POWERTRAIN BYR/60,000 POWERTRAIN BYR/60,000 POWERTRAIN COMPONENTS IF EQUIPPED COMPONENTS IF EQUIPPED COMPONENTS IF EQUIPPED CONS/OTHER C	fueleconomy.gov Calculate personalized estimates and compare vehicles
	RAMP ONE RH12 RAMP TWO	RAIL	L MSRP \$28,975.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right	
		ne Federal Automobile line, License, and Title Fees, uded. Dealer installed SC102 N	it for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine e lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

