HRM-010723 <sub>FL</sub>	9-NORMAL,NB,110723,SB171	715	UTC U CERT CERT CERT TRD R	W FL AMP BUMP C	AMPBOOKEXFLROTA 6
ford.com	HICLE DESCRIPTION MAVERICK 2025 XLT FWD 121" WHEELBASE 2.5L HYBRID ENGINE CONTINUOUSLY VARIABLE T	EXTERIOR SHADOW INTERIOR RANS NAVY PIE	SR <b>A493</b> BLACK FR - MED SLATE TRIM	17	EPA DOT Fuel Economy and E Fuel Economy MPG Small F MPG. T
STANDARD EQUIPMENT INCLUDED EXTERIOR • CARGO BOX TIE DOWN HOOKS • DAYTIME RUNNING LAMPS • DOOR HANDLES - BLACK • EASY FUEL® CAPLESS FILLER • ENCLOSED BED STORAGE • FLEXBEDTM STORAGE SYSTEM • HEADLAMPS - WIPER ACTIVATED • HEADLAMPS - LED AUTO HI-BEAM • HEADLAMPS - LED AUTO ON/OFF • LED REFLECTOR HEADLAMPS • POWER MIRRORS • POWER TAILGATE LOCK • TRAILER TOW HITCH • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 300A OPTIONAL EQUIPMENT/OTHER XLT LUXURY PACKAGE · POWER 8-WAY DRIVER SEAT 50 STATE EMISSIONS · FORD CO-PILOT360 . REAR PARKING SENSORS	INTERIOR • 1-TOUCH DOWN DRIVER WINDOW • 2ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE • 8.0" PRODUCTIVITY SCREEN • CRUISE CONTROL • DUAL USB • MANUAL A/C, SINGLE ZONE • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • POWERPOINTS - 12V • ROTARY GEAR SHIFT DIAL • UNIQUE CLOTH BUCKET SEATS • VINYL SOFT CONSOLE LID (MSRP)	BASE F TOTAL TOTAL	I-FI M SECURILOCK® ANTI-TH TIRE PRESSURE MONIT B WARRANTY • 3YR/36,000 BUMPER / E • 5YR/60,000 POWERTRA • 5YR/60,000 ROADSIDE / • 8YR/100,000 HYBRID UN -COMPONENTS IF EQUI	SYSTEM IEFT SYS SYS BUMPER IN ASSIST VIQUE	Open open dag iver 35   combined city/hwy city 35   ighway 36 ighway   3.6 gallons per 100 miles Image: State
	RAMP ONE RH35 RAMP TWO	RAIL	TAL MSRP \$33,77 Whether you decide to lease or vehicle, you'll find the choices t	finance your bat are right	3FTTW8H33SRA4931
	State and Local taxes are not	#: 24-8826 O/T 2 Ford C	redit for you. See your dealer for det www.ford.com/finance. 71 N RB 2X 550 010723 02 17	ails or visit	WARNING: Operating, servicing and maintaining a vehicle can expose you to chemicals including engineed, which are known to the State of California to cause of To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash for more information go to www.P65Warnings.ca.gov/past

