HRM-004606 AZ	9-NORMAL, NB, 104606, SE301 <b>195</b>		CERTCERTCERT TRD RAMPB		1100
	2025 XLT FWD 121" WHEELBASE 2.5L HYBRID ENGINE POWER-SPLIT ELECTRIC CVT	EXTERIOR DESERT S INTERIOR NAVY PIEF	SR B0668	37	EPA DOT Fuel Economy and En   Fuel Economy Small Picku   MPG Small Picku
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • CARGO BOX TIE DOWN HOOKS • DAYTIME RUNNING LAMPS • DOOR HANDLES - BLACK • EASY FUEL® CAPLESS FILLER • ENCLOSED BED STORAGE • FLEXBED <sup>TM</sup> STORAGE SYSTEM • HEADLAMPS - WIPER ACTIVATED • HEADLAMPS - LED AUTO HI-BEAM • HEADLAMPS - LED AUTO ON/OFF • LED REFLECTOR HEADLAMPS • POWER MIRRORS • POWER MIRRORS • POWER TAILGATE LOCK • TRAILER TOW HITCH • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 300A OPTIONAL EQUIPMENT/OTHER FLR LNRS WITHOUT CARPETED MATS XIT LUXURY PACKAGE • POWER 8-WAY DRIVER SEAT 50 STATE EMISSIONS DEALE INTRUCK BED LIGHTING Radside Assistance Kit First Aid Kit Tailgate Lock Wheel Lock Kit SecuriCodeÖ Keyless-Entry Keyp	INTERIOR • 1-TOUCH DOWN DRIVER WINDOW • 2ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE • 8.0" PRODUCTIVITY SCREEN • CRUISE CONTROL • DUAL USB • MANUAL A/C, SINGLE ZONE • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • POWERPOINTS - 12V • ROTARY GEAR SHIFT DIAL • UNIQUE CLOTH BUCKET SEATS • VINYL SOFT CONSOLE LID (MSRP)	BASE PR TOTAL O TOTAL V	FI PERIMETER ALARM SECURILOCK® ANTI-THEFT T TIRE PRESSURE MONIT SYS WARRANTY • 3YR/36,000 BUMPER / BUM • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSI • 8YR/100,000 HYBRID UNIQU -COMPONENTS IF EQUIPPE	TEM T SYS S IPER IST JE ED	Image: Signer of the search of the searc
	RAMP ONE CA4R RAMP TWO	CONVOY Scan get n	AL MSRP \$35,345. The QR Code to	.00	Star ratings range from 1 to 5 stars ( * * * * *), w Source: National Highway Traffic Safety Admin www.safercar.gov or 1-888-327-4 3FTTW8H34SRB06687
	This label is affixed pursuant to th Information Disclosure Act. Gaso State and Local taxes are not inclu options or accessories are not inclu	e Federal Automobile line, License, and Title Fees, uded. Dealer installed SE301	N RB 2X 560 004606 05 30 25		lead, which are known to the State of California to cause canc To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

