HRM-009552 AL	9-NORMAL, NB, 109552, SF241 759		CERTCERTCERT TRD RAMPBUMPCAI	
	2025 XLT FWD 121" WHEELBASE 2.5L HYBRID ENGINE POWER-SPLIT ELECTRIC CVT	EXTERIOR VELOCITY BI INTERIOR NAVY PIER -	SR B21281	EPA DOT Fuel Economy and En Fuel Economy Fuel Economy MPG. The
STANDARD EQUIPMENT INCLUDED EXTERIOR • CARGO BOX TIE DOWN HOOKS • DAYTIME RUNNING LAMPS • DOOR HANDLES - BLACK • EASY FUEL® CAPLESS FILLER • ENCLOSED BED STORAGE • FLEXBED™ STORAGE SYSTEM • HEADLAMPS -WIPER ACTIVATED • HEADLAMPS -LED AUTO HI-BEAM • HEADLAMPS-LED AUTO ON/OFF • LED REFLECTOR HEADLAMPS • POWER MIRRORS • POWER MIRRORS • POWER TAILGATE LOCK • TRAILER TOW HITCH • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 300A OPTIONAL EQUIPMENT/OTHER 50 STATE EMISSIONS FORD CO-PILOT360® 1.0 .REAR PARKING SENSORS	INTERIOR 1-TOUCH DOWN DRIVER WINDOW 2ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE 8.0" PRODUCTIVITY SCREEN CRUISE CONTROL 0 DUAL USB MANUAL A/C, SINGLE ZONE PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS POWERPOINTS - 12V ROTARY GEAR SHIFT DIAL UNIQUE CLOTH BUCKET SEATS VINYL SOFT CONSOLE LID MSRP	TOTAL VEH		fueleconomy.gov Calculate personalized estimates and compare vehicles GOVERNMENT 5-STAR SAFET
				Overall Vehicle Score Image: Additional state of the combined ratings of frontal, side and rollows Should ONLY be compared to other vehicles of similar sizes of the compares of the compare
	RAMP ONE RA3H	ΤΟΤΑΙ	_ MSRP \$33,135.00	3FTTW8H37SRB21281
	RAMP TWO		The QR Code to	WARNING: Operating, servicing and maintaining a provide the service of california to cause california to california to cause california to california to california to cause california to california to cause california to cause california to cause california to cause california to california to california to cause california to cal
	This label is affixed pursuant to th Information Disclosure Act. Gase State and Local taxes are not incl options or accessories are not in	he Federal Automobile Jline, License, and Title Fees, uded. Dealer installed SF241 N	RB 2X 560 009552 06 24 25	lead, which are known to the State of California to cause ca To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash ye For more information go to www.P65Warnings.ca.gov/pass

