| HRM-010397 он | S Holdman Harrison | 176 | RT CERT CERT TRD RAMP BUMP C | AMP BOOK EXFL ROTA 00 5844/1 |
|---------------|--|---|--|---|
| | INTERIOR • 1-TOUCH DOWN DRIVER WINDOW • 2ND ROW BENCH FLIP-UP W/ UNDER-SEAT STORAGE • 8.0" PRODUCTIVITY SCREEN • CRUISE CONTROL • DUAL USB • MANUAL A/C, SINGLE ZONE • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • POWER LOCKS AND WINDOWS • POWER POINTS - 12V • ROTARY GEAR SHIFT DIAL • UNIQUE CLOTH BUCKET SEATS • VINYL SOFT CONSOLE LID (MSRP) | <section-header><section-header><section-header><section-header><section-header></section-header></section-header></section-header></section-header></section-header> | SAFETY/SECURITY • AIRBAGS - SAFETY CANOPY® • BELT-MINDER CHIME • LATCH CHILD SAFETY SYSTEM • PERIMETER ALARM • SECURILOCK® ANTI-THEFT SYS • TIRE PRESSURE MONIT SYS WARRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSIST • 8YR/100,000 HYBRID UNIQUE • COMPONENTS IF EQUIPPED MINO (MSRP) * 28,895.00 * 28,895.00 * 20,705.00 | Field Economy Fuel Economy MPG MPG MPG MPG MPG MPG MPG MPG |
| | RAMP ONE | | SPD \$21 200 00 | Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★★★★), with Source: National Highway Traffic Safety Administ www.safercar.gov or 1-888-327-423 3FTTW8H39SRA12823 |
| | СН5М | | ISRP \$31,300.00 ether you decide to lease or finance your | |
| | | 48-0777 O/T 5C Credit for | icle, you'll find the choices that are right you. See your dealer for details or visit w.ford.com/finance. | WARNING: Operating, servicing and maintaining a passed vehicle can expose you to chemicals including engine exh lead, which are known to the State of California to cause cancer a |
| | This label is affixed pursuant to f Information Disclosure Act. Gas State and Local taxes are not inc | soline, License, and Title Fees, SP | ECIAL ORDER 2X 540 010397 11 26 24 | To minimize exposure, avoid breathing exhaust, do not idle the ere vehicle in a well-ventilated area and wear gloves or wash your has For more information go to www.P65Warnings.ca.gov/passenger |

