
120220118 1045 BLEND 1045

Go Further ford.com	STANG GT COUPE PREMIUM SSENGER SPORTS CAR TI-VCT V8: GT 450HP EED MANUAL TRANSMISS	S INTI	R ERIOR SHADOW BLACK ERIOR EBONY LTHR TRIM	5 1050 Power seats	86	EPA DOT Fuel Economy and En Fuel Economy MPG. The MPG. The
FOG LAMPS-LED AMBIEL HEADLAMPS - AUTOLAMP AUTOD (ON/OFF) DUAL I HEADLAMPS- LED WITH DUAL-2 SIGNATURE LIGHTING AUTO C HOOD VENTS HTD LT MIRRORS - HTD/PWR GLASS/ W/CRU MAN-FOLD/TURN SIG/MEM ILLUMI PONY PROJECTION LAMPS POWEF TAILLAMPS-LED W/SEQUENTIAL POWEF TURN SIGNAL SMART	B D DIGITAL IP CLUSTER IT LIGHTING IM REARVIEW MIRROR LUM VANITY MIRRORS ONE ELECTRONIC LIMATE CONTROL HR WRAPPED STR WHL SE AND AUDIO CTRLS VATED SILL PLATES LOCKS AND WINDOWS POINTS - 12V CHARGING USB PORT(2) OLD REAR SEAT P 00 00 00 00	EUNCTIONAL • ELECTRONIC PWR / • FORD CO-PILOT360 • FORDPASS™ CONN • INDEPENDENT REAR • INTELLIGENT ACCE BUTTON START • LIMITED SLIP REAR • REAR PARKING SEN • REAR VIEW CAMER, • SELECTABLE DRIVE • SIRIUSXM® - SVC N • SYNC3® 8" SCRN W • TRACK APPS™ • UNIVER GARAGE DO	ASST STEER IECT 4GWI-FI R SUSPEN SS W/PUSH AXLE AXLE MODES I/A AK&HI I/A AK&HI I/A PPLINK® OOR OPENER • 5	"Her "Ptions/other"	E FRONT RTAIN IT SYS SYSTEM TI THEFT RT SYS BUMPER IN	Image: A fig: A fig
ACTIVE VALVE PERFORMANCE EXH 995 ENGINE BLOCK HEATER 150 50 STATE EMISSIONS NO CHAR	00		TOTAL MS	RP \$54,28	5.00	Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Rollover Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★ ★ ★ ★), w Source: National Highway Traffic Safety Admin www.safercar.gov or 1-888-327- 1FA6P8CF5N5105086
	CA72	CONVOY	Wheth	er you decide to lease or , you'll find the choices t	finance your	WARNING: Operating, servicing and maintaining a pa
	This label is affixed pursuant to t Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not in	oline, License, and Title Fees, luded. Dealer installed	FORD CREDIT for you www.f	y. See your dealer for deta ord.com/finance. CIAL ORDER (220 000195 01 10	ails or visit	vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle th vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passer



1202201181045