



ford.com

VEHICLE DESCRIPTION

SUPER DUTY

2023 F550 4X4 CREW CHASSIS  
XL 179" WB CHASSIS CAB  
6.7L POWER STROKE V8 DIESEL  
10-SPEED AUTO TORQSHIFT

PE

C85898

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- HEADLAMPS - AUTOLAMP (ON/OFF)
- HEADLAMPS -WIPER ACTIVATED
- MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS
- ROOF CLEARANCE LIGHTS
- TOW HOOKS
- TRAILER BRAKE CONTROLLER
- TRAILER SWAY CONTROL
- TRAILER TOW WIRE HARNESS
- WIPERS- INTERMITTENT

INTERIOR

- 4.2" PRODUCTIVITY SCREEN
- AIR COND, MANUAL FRONT
- BLACK VINYL FLOOR COVERING
- OUTSIDE TEMP DISPLAY
- PARTICULATE AIR FILTER
- POWER LOCKS AND WINDOWS
- STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS
- UPFITTER SWITCHES

FUNCTIONAL

- 4-WHEEL ANTILOCK BRAKE SYS
- FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM
- HILL START ASSIST
- JEWEL EFFECT HEADLAMPS
- REMOTE KEYLESS ENTRY
- STABILIZER BAR, FRONT/REAR
- SYNC®4 W/8" SCREEN

SAFETY/SECURITY

- ADVANCETRAC™ WITH RSC®
- AIRBAGS - SAFETY CANOPY®
- BELT-MINDER CHIME
- DRIVER/PASSENGER AIR BAGS
- SECURILOCK® ANTI-THEFT SYS
- SOS POST-CRASH ALERT SYST™

WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST
- 5YR/100,000 DIESEL ENGINE

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

PREFERRED EQUIPMENT PKG.660A

6.7L POWER STROKE V8 DIESEL

10-SPEED AUTO TORQSHIFT

4.30 RATIO LIMITED SLIP AXLE

RAPID HEAT SUPPLEMENTAL HEATER

FRONT LICENSE PLATE BRACKET

FORD PRO UPFIT INTEGR REMOVAL

19500# GVWR PACKAGE

50 STATE EMISSIONS

120V/400W OUTLET

SPARE TIRE AND WHEEL

HIGH CAPACITY TRAILER TOW PKG

JACK

40 GAL AFT OF AXLE FUEL TNK

410 AMP ALTERNATOR

EXTRA HEAVY SERVICE SUSPENSION

PAYLOAD PLUS PACKAGE UPGRADE

DUAL BATTERY

CLOTH 40/20/40 SEAT

PRIVACY GLASS

XL CHROME PACKAGE

.BACKGLASS DEFROST

.POWER SLIDING REAR WINDOW

.FOG LAMPS

.BRIGHT GRILLE

.REMOTE START SYSTEM

(MSRP)

9,995.00

NO CHARGE

395.00

250.00

NO CHARGE

- 400.00

NO CHARGE

175.00

350.00

580.00

NO CHARGE

NO CHARGE

NO CHARGE

125.00

1,155.00

NO CHARGE

315.00

225.00

PRICE INFORMATION

BASE PRICE

TOTAL OPTIONS/OTHER

57,690.00

13,165.00

TOTAL VEHICLE & OPTIONS/OTHER

DESTINATION & DELIVERY

70,855.00

1,895.00

(MSRP)

	RAMP ONE		TOTAL MSRP \$72,750.00
	RW73		
	RAMP TWO	RAIL	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit <a href="http://www.ford.com/finance">www.ford.com/finance</a> .
		ITEM #: 41-0111 O/T 1	
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		SPECIAL ORDER PE042 N RB 2X 340 000752 05 04 23

EPA DOT

Fuel Economy and Environment

FUEL ECONOMY RATINGS NOT REQUIRED ON THIS VEHICLE

fueleconomy.gov

Calculate personalized estimates and compare vehicles





The FordPass® Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.\*\* See in-vehicle settings for connectivity options.

\*Based on 1977–2022 CY total sales.  
\*\*FordPass Connect (optional on select vehicles), the FordPass App and complimentary Connected Service are required for remote features (see FordPass Terms for details). Connected service and features depend on compatible AT&T network availability. Evolving technology/cellular networks/vehicle capability may limit functionality and prevent operation of connected features. Connected service excludes Wi-Fi hotspot.



FORD PROTECT®  
Continued Service Plan

Insist on Ford Protect! The only extended service plan fully backed by Ford and honored at every Ford dealership in the U.S., Canada and Mexico. See your Ford dealer or visit [www.FordOwner.com](http://www.FordOwner.com).



**WARNING:** Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to [www.P65Warnings.ca.gov/passenger-vehicle](http://www.P65Warnings.ca.gov/passenger-vehicle).

SCAN QR TEXT 1FPEC85898 TO 48028

Msg & Data rates may apply. Text HELP for help



[www.ford.com/help/privacy-terms/](http://www.ford.com/help/privacy-terms/)