




**EXTERIOR**  
**OXFORD WHITE**  
**INTERIOR**  
**MEDIUM DARK SLATE CLOTH**

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST
- 5YR/100,000 DIESEL ENGINE

NO CHARGE	350.00
	280.00
NO CHARGE	1,095.00
NO CHARGE	1,155.00
	415.00

## 1,995.00

	RAMP ONE		<b>TOTAL MSRP</b> <b>\$66,045.00</b>
	CS1P		
	RAMP TWO	CONVOY	 <p>Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit <a href="http://www.ford.com/finance">www.ford.com/finance</a>.</p>
		ITEM #: 71-W860 O/T 1	
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		<b>SPECIAL ORDER</b> RB262 N RB 2X 425 000736 02 26 24

### Calculate personalized estimates and compare vehicles




**The FordPass® Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.\*\* See in-vehicle settings for connectivity options.**

**\*Based on 1977–2022 CY total sales.**  
**\*\*FordPass Connect (optional on select vehicles), the FordPass App and complimentary Connected Service are required for remote features (see FordPass Terms for details). Connected service and features depend on compatible AT&T network availability. Evolving technology/cellular networks/vehicle capability may limit functionality and prevent operation of connected features. Connected service excludes Wi-Fi hotspot.**



**Insist on Ford Protect!** The only extended service plan fully backed by Ford and honored at every Ford dealership in the U.S., Canada and Mexico. See your Ford dealer or visit [www.FordOwner.com](http://www.FordOwner.com).



 **WARNING:** Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to [www.P65Warnings.ca.gov/passenger-vehicle](http://www.P65Warnings.ca.gov/passenger-vehicle).

SCAN OR TEXT 1FREC55761 TO 48028

**Msg & Data rates may apply. Text HELP for help**



[www.ford.com/help/privacy-terms/](http://www.ford.com/help/privacy-terms/)