



ford.com

VEHICLE DESCRIPTION

SUPER DUTY

2023 F550 4X4 SUPER CHASSIS
XLT 168" WB CHASSIS CAB
7.3L DEVCT NA PFI V8 ENGINE
10-SPEED AUTO TORQSHIFT

EXTERIOR
OXFORD WHITE

INTERIOR
MEDIUM DARK SLATE CLOTH

PE C50857

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- BUMPER - CHROME
- HEADLAMPS - AUTOLAMP (ON/OFF)
- REAR PRIVACY GLASS
- ROOF CLEARANCE LIGHTS
- TOW HOOKS
- TRAILER BRAKE CONTROLLER
- TRAILER SWAY CONTROL
- TRAILER TOW WIRE HARNESS

INTERIOR

- 120V OUTLET
- 1TOUCH UP/DOWN DR/PASS WIN
- AIR COND, MANUAL FRONT
- CLOTH SUN VISORS
- OUTSIDE TEMP DISPLAY
- PARTICULATE AIR FILTER
- POWER LOCKS AND WINDOWS
- STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS
- UPFITTER SWITCHES
- UPPER GLOVEBOX STORAGE

FUNCTIONAL

- 4-WHEEL ANTILOCK BRAKE SYS
- FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM
- HILL START ASSIST
- JEWEL EFFECT HEADLAMPS
- REMOTE KEYLESS ENTRY
- STABILIZER BAR, FRONT/REAR
- SYNC®4 W/8" SCREEN

SAFETY/SECURITY

- ADVANCED SECURITY PACK
- ADVANCETRAC™ WITH RSC®
- AIRBAGS - SAFETY CANOPY®
- BELT-MINDER CHIME
- DRIVER/PASSENGER AIR BAGS
- SOS POST-CRASH ALERT SYS™

WARRANTY

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST
- 5YR/100,000 DIESEL ENGINE

INCLUDED ON THIS VEHICLE

OPTIONAL EQUIPMENT/OTHER

PREFERRED EQUIPMENT PKG.663A

10-SPEED AUTO TORQSHIFT

4.88 RATIO LIMITED SLIP AXLE

XLT VALUE PACKAGE

.BACKGLASS DEFROST

.FOG LAMPS

.ADJUSTABLE GAS/BRAKE PEDAL

.REMOTE START SYSTEM

.HEATED FRONT SEATS

.8-WAY POWER SEAT-DRIVER

FORD PRO UPFIT INTEGR REMOVAL

19500# GVWR PACKAGE

50 STATE EMISSIONS

PRO POWER ONBOARD - 2KW

AMBULANCE PREP PACKAGE

POWERSCOPE TRAILER TOW MIRROR

UTILITY LIGHTING SYSTEM

POLISHED FORGED ALUM 19.5" WHL

PAYLOAD PLUS PACKAGE UPGRADE

REAR VIEW CAMERA & PREP KIT

(MSRP)

NO CHARGE

395.00

2,155.00

- 400.00

NO CHARGE

985.00

1,205.00

280.00

1,095.00

1,155.00

415.00

PRICE INFORMATION

BASE PRICE

\$57,805.00

TOTAL OPTIONS/OTHER

7,285.00

TOTAL VEHICLE & OPTIONS/OTHER

65,090.00

DESTINATION & DELIVERY

1,895.00

	RAMP ONE		TOTAL MSRP \$66,985.00
	RB2M		
	RAMP TWO	RAIL	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance .
		ITEM #: 44-D113 O/T 5C	
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		SPECIAL ORDER PC151 N RB 2X 330 001982 03 15 23

EPA DOT

Fuel Economy and Environment

FUEL ECONOMY RATINGS NOT REQUIRED ON THIS VEHICLE

fueleconomy.gov

Calculate personalized estimates and compare vehicles



46 BUILT YEARS TOUGH F-SERIES AMERICA'S BEST SELLING TRUCKS

The FordPass® Connect modem is active and sending vehicle data (e.g., diagnostics) to Ford.** See in-vehicle settings for connectivity options.

*Based on 1977–2022 CY total sales.
**FordPass Connect (optional on select vehicles), the FordPass App and complimentary Connected Service are required for remote features (see FordPass Terms for details). Connected service and features depend on compatible AT&T network availability. Evolving technology/cellular networks/vehicle capability may limit functionality and prevent operation of connected features. Connected service excludes Wi-Fi hotspot.



FORD PROTECT®
Continued Service Plan

Insist on Ford Protect! The only extended service plan fully backed by Ford and honored at every Ford dealership in the U.S., Canada and Mexico. See your Ford dealer or visit www.FordOwner.com.

1FD0X5HN2PEC50857



⚠

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

SCAN OR TEXT 1FPEC50857 TO 48028

Msg & Data rates may apply. Text HELP for help



www.ford.com/help/privacy-terms/