	SUPER DUT		RE D62343	California Air Resources Board
ford.com	XL 179" WB CHASSIS CAB 6.7L POWER STROKE V8 DIE 10-SPEED AUTO TORQSHIFT	OXFORD WH SEL INTERIOR	ITE RK SLATE VINYL	Environment
STANDARD EQUIPMENT INCLUDED AT				These ratings are not directly comparable to For information on how to compa
EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE OTIONAL EQUIPMENT PKG.640A 6.7L POWER STROKE V8 DIESEL 10-SPEED AUTO TORQSHIFT LT245/75R17E BSW ALL-TERRAIN 4.10 RATIO LIMITED SLIP AXLE FRATHOR UNINIG BOARDS 1400# GVWR PACKAGE SKID PLATES 50 STATE EMISSIONS 120V/400W OUTLET SPARE TIRE AND WHEEL INTERIOR WORK SURFACE CHTER HIGH MOUNT STOP LAMP JACK 40 GAL AFT OF AXLE FUEL TNK 350 AMP ALTERNATOR EXTERIOR BACKUP ALARM DUAL BATTERY REAR VIEW CAMERA & PREP KIT	INTERIOR • 4.2" PRODUCTIVITY SCREEN • AIR COND, MANUAL FRONT • BLACK VINYL FLOOR COVERING • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS • UPFITTER SWITCHES • UPFITTER SWITC	TOTAL VEH		
		ΤΟΤΑ	L MSRP \$70,070.00	1FD8W3HT0RED62343
	RA5B	RAIL	Whether you decide to lease or finance you	r
	RAMP TWO	(I'ind)	vehicle, you'll find the choices that are right t for you. See your dealer for details or visit www.ford.com/finance.	t WARNING: Operating, servicing and maintaining a passer vehicle can expose you to chemicals including engine exhat lead, which are known to the State of California to cause cancer a
This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		asoline, License, and Title Fees, ncluded. Dealer installed RC221 N	SPECIAL ORDER I RB 2X 425 002459 03 22 24	R To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h

