KTP-000735 _{TX}	9-NORMAL, NB, 200735, RH152	10968	CERTCERTCERT	TRD RAMP BUMP CAI	MP BOOK EXFL ROTA
	SUPER DU 2024 F350 DRW 4X4 CRI XL 179" WB CHASSIS CA 6.7L POWER STROKE V8 10-SPEED AUTO TORQSI	EW CHAS EXT AB (3 DIESEL INTI	RE E7	8649	California Air Resources B Environm
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.640A 6.7L POWER STROKE V8 DIESEL 10-SPEED AUTO TORGSHIFT 3.73 RATIO REGULAR AXLE FRONT LICENSE PLATE BRACKET PLATFORM RUNNING BOARDS 14000# GVWR PACKAGE SKID PLATES 50 STATE EMISSIONS SPARE TIRE AND WHEEL JACK 40 GAL AFT OF AXLE FUEL TNK DUAL BATTERY REAR VIEW CAMERA & PREP KIT PRIVACY GLASS XL CHROME PACKAGE .BACKGLASS DEFROST .POWER SLIDING REAR WINDOW .FOG LAMPS .REMOTE START SYSTEM	NO EXTRA CHARGE 1NTERIOR • 4.2" PRODUCTIVITY SCREEN • AIR COND, MANUAL FRONT • BLACK VINYL FLOOR COVERIN • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS • UPFITTER SWITCHES • UPFITTER SWITCHES • UPFITTER SWITCHES • OCHARGE NO CHARGE NO CHARGE 15.00 225.00	HILL START ASSIST JEWEL EFFECT HEA	ADLAMPS ENTRY RONT/REAR	™ WITH RSC® ETY CANOPY® CHIME NGER AIR BAGS ANTI-THEFT SYS SH ALERT SYS™ MPER / BUMPER VERTRAIN ADSIDE ASSIST ESEL ENGINE (MSRP) \$55,720.00 12,030.00	These ratings are not directly compare For information on how to Protect the environment Greenhouse Gas Rating (tails (
	RAMP ONE RH80 RAMP TWO	RAIL ITEM #: 52-0622 O/T 2	TOTAL MSRP\$6Image: Second CreditWhether you decide to vehicle, you'll find the convenience of the you. See your dealer www.ford.com/finance	choices that are right r for details or visit	1FD8W3HT1REE786 WARNING: Operating, servicing and maintaining vehicle can expose you to chemicals including en lead, which are known to the State of California to cause
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		RH152 N RB 2X 430 000735		lead, which are known to the State of California to cause To minimize exposure, avoid breathing exhaust, do not vehicle in a well-ventilated area and wear gloves or was For more information go to www.P65Warnings.ca.gov/p

