OHI-000073 _{CA}		X 1F	DRF3HT3RDA11713	SUPER	MAIL	16
	HICLE DESCRIPTION SUPER DU 2024 F350 DRW 4X4 REC XL 169" WB CHASSIS CA 6.7L POWER STROKE V8 10-SPEED AUTO TORQSI AT NO EXTRA CHARGE	G CHAS EXTER AB OXF DIESEL INTERIO	IOR ORD WHITE	11713	These ratings are no	vironme
EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.640A 6.7L POWER STROKE V8 DIESEL 10-SPEED AUTO TORQSHIFT 3.73 RATIO REGULAR AXLE FRONT LICENSE PLATE BRACKET 14000# GVWR PACKAGE 50 STATE EMISSIONS 120V/400W OUTLET SPARE TIRE AND WHEEL DELETE JACK 40 GAL AFT OF AXLE FUEL TNK 350 AMP ALTERNATOR DUAL BATTERY REAR VIEW CAMERA & PREP KIT XL CHROME PACKAGE .FOG LAMPS .REMOTE START SYSTEM	INTERIOR AIR COND, MANUAL FRONT BLACK VINYL FLOOR COVERIN OUTSIDE TEMP DISPLAY PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS UPFITTER SWITCHES UPFITTER SWITCHES 9,995.00 NO CHARGE NO CHARGE NO CHARGE NO CHARGE 175.00 - 85.00 55.00 NO CHARGE NO CHARGE	HOTSPOT TELEMATICS • HILL START ASSIST • JEWEL EFFECT HEADLA • REMOTE KEYLESS ENT • STABILIZER BAR, FROM • SYNC®4 W/8" SCREEN • SYNC®4 W/8" SCREEN	r 5GWI-FI MODEM AMPS RY IT/REAR	AC [™] WITH RSC® SAFETY CANOPY® ER CHIME SSENGER AIR BAGS K® ANTI-THEFT SYS CRASH ALERT SYS™ BUMPER / BUMPER POWERTRAIN ROADSIDE ASSIST DIESEL ENGINE (MSRP) \$53,025.00 10,780.00		imary contributor to
	RAMP ONE RD27 RAMP TWO	RAIL	Whether you decid	\$65,800.00 e to lease or finance your the choices that are right ealer for details or visit	WARNING: Operating, se vehicle can expose you to lead, which are known to the Star	FDRF3HT3RDA1171
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		SPECIAL O R901 R 6B 2X 425 0000	RDER	lead, which are known to the State of California to cause To minimize exposure, avoid breathing exhaust, do not id vehicle in a well-ventilated area and wear gloves or wash For more information go to www.P65Warnings.ca.gov/page	

