OHI-000084 IN	48C 532 6B 2 2 LABL ADJ COV P	RCS B10 RAMP BUMP	1FDWE3FN7SDD04207	E-SERIES	MAIL	0. 33
	CLE DESCRIPTION E-SERIES 2025 E-350 CUTAWAY DR DRW 138 WB 7.3L V8 PREMIUM-RATED ELEC 6-SPD AOD W/TOW	ENG. INT	SD TERIOR DXFORD WHITE ERIOR MEDIUM FLINT VINYL	004207		onomy and En
STANDARD EQUIPMENT INCLUDED A EXTERIOR • AUXILIARY FUEL PORT • BUMPER, BLACK • HEADLAMPS - AUTOLAMP (DN/OFF) • INTERVAL WIPERS • IT225/75R16E BSW TIRES • SOLAR TINTED GLASS INCLUDED ON THIS VEHICLE DYIONAL EQUIPMENT PKG.780A .5TANDARD TRIM 7.3L V8 PREMIUM-RATED ENG. LT225/75R16E DRW HANKOOK 4.56 LIMITED SLIP AXLE XF5 HIGH-SERIES EXT UPGRADE PKG POWER EQUIPMENT GROUP STABILITY CONTROL ESC DELETE REAR VIEW CAMERA W/MIRROR RAW MATERIALS SURCHARGE FRONT ILCENSE PLATE BRACKET 11500# GVWR PACKAGE 50 STATE EMISSIONS CRUISE CONTROL TRAILER TOWING PKG CLASS I MIRRORS,MAN TLR TOW W/PWR GLS FRONT MAX GAWR B-PILLAR TRIM KIT DAYTIME RUNNING LIGHTS REMOTE KEYLESS ENT/PANIC ALARM	IND EXTRA CHARGE AIR CONDITIONING AM/FM RADIO W/ BLUETOOTH® BLACK VINYL FLOOR COVERING COVE BOX WITH POWERPOINT POWERPOINT - 12V (FRONT) STEERING - TILT/TELESCOPIC TACHOMETER VINYL FRONT HEADLINER VINYL SUN VISORS (MSRP) NO CHARGE NO CHARGE 240.00 135.00 230.00 40.00 75.00 25.00 NO CHARGE	• FLEET TELEMATICS	HR MODEM MODEM HR SMODEM HENDENT N HR HR HR HR HR HR HR HR HR HR	000 BUMPER / BUMPER 000 POWERTRAIN 000 ROADSIDE ASSIST (MSRP) \$38,045.00 2,100.00 5/OTHER 40,145.00 1,995.00 CE USE. 5 VOID IF	fueleconc Calculate personalized es	DUIRED O
	RAMP ONE RA79	RAIL	TOTAL MSRP	\$42,140.00		1FDWE3FN7SDD04207
	RAMP TWO FAIL ITEM #: 48-0212 O/T 59 This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		vehicle, you'll find the choices that are right Ford Credit for you. See your dealer for details or visit www.ford.com/finance. SPECIAL ORDER R907 R 6B 2X 515 000084 04 03 24		WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine of lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng	

