
OHI-000141 PA	16A 406 6B 2 LABL ADJ COV	XImage: second seco	1FDWE3FN8RDD06056	E-SERIES	MAIL	0 33
	ELE DESCRIPTION E-SERIES 2024 E-350 CUTAWAY I DRW 138 WB 7.3L V8 PREMIUM-RATE ELEC 6-SPD AOD W/TO	ED ENG. INT	RD D TERIOR DXFORD WHITE ERIOR MEDIUM FLINT CLOTH	06056		onomy and En
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • AUXILIARY FUEL PORT • BUMPER, BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • INTERVAL WIPERS • LT225/75R16E BSW TIRES • SOLAR TINTED GLASS	NO EXTRA CHARGE INTERIOR • AIR CONDITIONING • AM/FM RADIO W/ BLUETOOTH • BLACK VINYL FLOOR COVERII • GLOVE BOX WITH POWERPOI • POWERPOINT - 12V (FRONT) • STEERING - TILT/TELESCOPIC • TACHOMETER • VINYL FRONT HEADLINER • VINYL SUN VISORS	NG • FLEET TELEMATICS NT • TWIN I-BEAM INDE FRONT SUSPENSIO	HR • 4-WHEEL BRAKING PENDENT • DRIVER/P N • ELECTRO • TRACTION • 3YR/36,00 • 5YR/60,00	GAFETY BELTS ANTI-LOCK DISC SYSTEM ASSENGER AIR BAGS NIC STABILITY CNTRL N CONTROL	REG	OUIRED O
INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.780A. STANDARD TRIM 7.3L V8 PREMIUM-RATED ENG. LT225/75816E DRW HANKOOK 4.56 LIMITED SLIP AXLE XF5 HIGH-SERIES EXT UPGRADE PKG POWER WINDOWS AND LOCKS GROUP REAR VIEW CAMERA W/MIRROR RAW MATERIALS SURCHARGE FRONT LICENSE PLATE BRACKET 11500# GVWR PACKAGE 50 STATE EMISSIONS CRUISE CONTROL MIRRORS,MAN TLR TOW W/PWR GLS FRAME PUCKS (ISOLATORS) WIFI 4G LTE HOTSPOT DELETE CLOTH BUCKET SEATS B-PILLAR TRIM KIT REMOTE KEYLESS ENT/PANIC ALARM	(MSRP) NO CHARGE 270.00 100.00 465.00 495.00 NO CHARGE NO CHARGE NO CHARGE 240.00 230.00 50.00 - 20.00 NO CHARGE 75.00 250.00	tion of the second seco	PRICE INFORMATION BASE PRICE TOTAL OPTIONS/OTHER TOTAL VEHICLE & OPTIONS/O DESTINATION & DELIVERY NOT FOR AMBULANCE FORD WARRANTY IS V USED AS AN AMBULA	1,795.00		Stimates and compare vehicles
	Information Disclosure	RAIL ITEM #: 16-6003 O/T 2 Insuant to the Federal Automobile e Act. Gasoline, License, and Title Fees, are not included. Dealer installed		finance.	vehicle can expose	1FDWE3FN8RDD06056 mg, servicing and maintaining a pass you to chemicals including engine to State of California to cause cance id breathing exhaust, do not idle th area and wear gloves or wash you www.P65Warnings.ca.gov/passen

05/09/2024



he engine except as necessary, service your ur hands frequently when servicing your vehicle. nger-vehicle.

apply. Text HELP for help



www.ford.com/help/privacy-terms/