OHI-000217 PA 2	23C 042 6B 2 2 LABL ADJ COV P	RCS B10 RAMP BUMP	1FDXE4FN4PDD21919	E-SERIES	MAIL	00 431
	ELE DESCRIPTION ESERIES 2023 E-450 CUTAWAY DF DRW 176 WB 7.3L V8 PREMIUM-RATED ELEC 6-SPD AOD W/TOW	ENG. INTE	PD ERIOR XFORD WHITE ERIOR MEDIUM FLINT CLOTH	021919		conomy and Env L ECONON
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • AUXILIARY FUEL PORT • BUMPER, BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • INTERVAL WIPERS • LT225/75R16E BSW TIRES • SOLAR TINTED GLASS INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER 4003-384P01/01/22 LF030 PREFERRED EQUIPMENT PKG.782A STANDARD TRIM 7.3L V8 PREMIUM-RATED ENG. 4.56 RATIO REGULAR AXLE X83 POWER WINDOWS AND LOCKS GROUP RAW MATERIALS SURCHARGE FRONT LICENSE PLATE BRACKET 14500# GWWR PACKAGE 50 STATE EMISSIONS DRIVER ASSIST TECH PACKAGE INSTRUMENT PANEL ELEC MESSAGE FRONT MAX GAWR WIFI 4G LTE HOTSPOT DELETE CLOTH BUCKET SEATS REMOTE KEYLESS ENT/PANIC ALARM	NO EXTRA CHARGE INTERIOR AM/FM RADIO W/ BLUETOOTH® BLACK VINYL FLOOR COVERING GLOVE BOX W/ 12V PWR PT POWERPOINT - 12V (FRONT) STEERING - TILT/TELESCOPIC TACHOMETER VINYL FRONT HEADLINER VINYL SUN VISORS (MSRP) NO CHARGE SUB CHARGE NO CHARGE NO CHARGE SUB CHARGE NO CHARGE SUB CHARGE AG5.00 NO CHARGE SUB CH		N COOLER HR MODEM SENDENT N SENDENT N SENDENT N STRACTION SYR/360 SYR/60,	000 BUMPER TO BUMPER 000 POWERTRAIN 000 ROADSIDE ASSIST (MSRP \$38,565.00 2,060.00 5/OTHER 40,625.00 1,295.00 CE USE. VOID IF	b b c alculate personalized	QUIRED O
	RAMP ONE CL07 RAMP TWO	CONVOY	TOTAL MSRP	\$41,920.00	r	1FDXE4FN4PDD21919
	ITEM #: 23-6015 O/T 59 This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance. SPECIAL ORDER R497 R 6B 2X 325 000217 08 31 22		WARNING: Operating, servicing and maintaining a pase vehicle can expose you to chemicals including engine e lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng	

