CHI-002483 _{CA}	9-NORMAL,NB,102483,ND131 208	4 120220422 1984 UTC	U R CA T CERT TRD RAMP BUMP C.	AMPBOOKEXFLROTA 828/
	ICLE DESCRIPTION EXPLORER ST 4WD 2022 EXPLORER ST 4WD 119" WHEELBASE 3.0L ECOBOOST V6 ENGINE 10-SPEED AUTO TRANSMISSION	EXTERIOR AGATE BLACK ME INTERIOR		EPA DOT Fuel Economy and Environment Fuel Economy Standard SU MPG. The beside
STANDARD EQUIPMENT INCLUDED A EXTERIOR • EASY FUEL® CAPLESS FILLER • FRT/RR SKID PLATE ELEMENTS • GRILLE - BLACK MESH INSERT • HEAD/TAILLAMPS - BLACKOUT • HEADLAMPS - AUTO LED • LED SIGNATURE LIGHTING • LWR BODYSIDE CLADDING-BLK • PRIVACY GLASS - REAR DOORS • QUAD TIP DUAL EXHAUST • REAR INT WIPER/WASH/DFRST • TAILLAMPS/FOG LAMPS - LED • TRAILER SWAY CONTROL	AT NO EXTRA CHARGE INTERIOR • 12" LCD DIGITAL IP CLUSTER • 1ST/2ND RW FLR MATS-CARPET • 1TOUCH UP/DOWN DR/PASS WIN • DUAL ILLUM VIS VANITY MIRR • HTD LTHR WRAPPED STEER WHL W/LOGO, MOUNTED CONTROLS • POWERPOINTS - 12V • ROTARY GEAR SHIFT DIAL • SPORT BUCKET FRONT SEATS • TRI-ZONE ELECTRNC TMP CTRL • USB A(1)/C(1)-1ST/2ND ROWS		ADVANCETRAC [™] WITH RSC® AIRBAG-DRIVER/PASS KNEE AIRBAGS - DUAL STAGE FRONT AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - SAFETY CANOPY® INDIV TIRE PRESS MONIT SYS LATCH CHILD SAFETY SYSTEM PERIMETER ALARM PERSONAL SAFETY SYSTEM [™] SOS POST-CRASH ALERT SYS [™] <u>VARRANTY</u> 3YR/36,000 BUMPER / BUMPER	 Letter the second second
INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 401A •ST HIGH PACKAGE	(MSRP) 4,995.00	• PRICE INFORMAT BASE PRICE	\$50,245.00	Actual results will vary for many reasons, including driving convehicle. The average new vehicle gets 27 MPG and costs \$6,500 based on 15,000 miles per year at \$2.35 per gallon. MPGe is mil emissions are a significant cause of climate change and smog.
•FORD CO-PILOT360 ASSIST+ OPTIONAL EQUIPMENT/OTHER P275/45R21 A/S BSW TIRES 21" ALUMINUM WHEELS PERFORMANCE BRAKES 2ND RW SPLT BENCH W/E-Z ENTRY 50 STATE EMISSIONS TWIN PANEL MOONROOF 2ND ROW HTD STS CNTRLS CREDIT PREMIUM TECHNOLOGY PACKAGE .14 SPEAKERS .10.1" LCD PORTRAIT TOUCHSCRN .MULTICONTOUR FRONT SEATS ROOF-RACK SIDE RAILS, BLACK REAR AUXILIARY CNTRLS CREDIT FRONT LICENSE PLATE BRACKET	NO CHARGE NO CHARGE 1,695.00 - 100.00 1,295.00 250.00 - 50.00 NO CHARGE	1-day driving experience 1 guest experience 1 guest experience 1-night hotel stay Welcome dinner reception for Breakfast for you and a guest Catered lunch Exclusive ST SUV Experience Memories to last a lifetime For all program details and to re or contact the Ford Performance The complimentary ST SUV Experience Eligible participants who purchased ar calendar year from the date of delivery	hase is an riving program. V Experience registration: you and a guest	Calculate personalized estimates and compare vehicles GOVERNMENT 5-STAR SAFETY Overall Vehicle Score Not Rate Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size and Frontal Driver Not Rate Crash Passenger Not Rate Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size and Side Front seat * * * * Crash Rear seat * * * * Based on the risk of injury in a side impact. Should ONLY be compared to other vehicles of similar size and Side Front seat * * * * Crash Rear seat * * * * Based on the risk of injury in a side impact. Star ratings range from 1 to 5 stars (* * * * *), with Source: National Highway Traffic Safety Adminis www.safercar.gov or 1-888-327-423 Star ratings range from 1 to 5 stars (* * * * *)
	ITEM #:	1-2244 OCT 2	SRP \$59,825.00 ther you decide to lease or finance your le, you'll find the choices that are right bu. See your dealer for details or visit ford.com/finance.	Image: Constraint of the state of California to cause cancer WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ex lead, which are known to the State of California to cause cancer
	This label is affixed pursuant to the Information Disclosure Act. Gasoli State and Local taxes are not inclue options or accessories are not incl	e Federal Automobile ine, License, and Title Fees, ded. Dealer installed ND131 N BB 2	X 250 002483 04 13 22	lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge
				120220422

