CHI-003094 _{TX}	9-NORMAL, NB, 103094, PM111 166	63 120231218 0836	UTC U W TX CERT CERT CERT TRD RAMP BUMP (CAMPBOOKEXFLROTA 836/
	E DESCRIPTION XPLORER 2023 EXPLORER XLT RWD 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSION	INTERIOR	PG C42674 NET TINTED CC UNIQUE CLOTH SEAT	Fuel Economy and Env Fuel Economy MPG. The bes 214 2128
<section-header><section-header><section-header></section-header></section-header></section-header>	NTERIOR 110UCH UP/DOWN DR/PASS WIN 3RD ROW - 50/50 FOLD FLAT UAL ILLUM VIS VANITY MIRR HEATED CLOTH FRONT SEATS IP CLUSTER 6.5" LCD SCREEN LEATHER WRAPPED STR WHEEL POWER DRIVER SEAT - 10 WAY POWER PASS SEAT - 4-WAY OWERPOINTS - 12V ROTARY GEAR SHIFT DIAL TILT/TELESCOPING STEERING WWHEEL MOUNTED CONTROLS TRI-ZONE ELECTRNC TMP CTRL USB A(1) AND C(1)-1ST ROW 495.00 NO CHARGE 20.00 100.00 NO CHARGE 		\$38,570.00	combined city/hwycityhighway4.2gallons per 100 milesAnnual fuelCOST\$1,800\$
		ΤΟΤΑΙ	. MSRP \$40,540.00	1FMSK7DHXPGC42674
	RAMP TWO		Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	vehicle can expose you to chemicals including engine exh lead, which are known to the State of California to cause cancer a
	This label is affixed pursuant to t Information Disclosure Act. Gase State and Local taxes are not incl options or accessories are not ir	oline, License, and Title Fees, luded. Dealer installed PM111 N	RB 2X 360 003094 12 11 23	To minimize exposure, avoid breathing exhaust, do not idle the ervehicle in a well-ventilated area and wear gloves or wash your har For more information go to www.P65Warnings.ca.gov/passenger-

1202312180836

05/30/2024

