CHI-006076 ND	9-NORMAL, NB, 106076, RL131	165 120241121 3362	UTC     U     W     ND       CERT CERT CERT     TRD     RAMP BUMP	CAMPBOOKEXFLROTA 02
Ford.com	EHICLE DESCRIPTION EXPLORER ACTIVE 4W 2025 EXPLORER ACTIVE 4W 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISS	CARBONIZED INTERIOR	SG B01562 O gray metallic Ray activex seats	EPA DOT Fuel Economy and Env Fuel Economy MPG. The be
STANDARD EQUIPMENT INCLUDE EXTERIOR • CLASS III TRAILER TOW PKG • EASY FUEL® CAPLESS FILLER • HEADLAMPS - AUTO LED • MIRRORS-MAN-FOLD DUAL PWR HEATED WITH APPROACH LAMPS • POWER LIFTGATE • PRIVACY GLASS - REAR DOORS • REAR INT WIPER/WASH/DFRST • REAR SPOILER, BODY COLOR • ROOF-RACK SIDE RAILS-BLACK • TAILLAMPS-LED • TRAILER SWAY CONTROL • VARIABLE INTERVAL WIPERS INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 200A OPTIONAL EQUIPMENT/OTHER P255/55R20 A/S BSW TIRES 2ND RW SPLT BENCH W/E-Z ENTRY ENGINE BLOCK HEATER 50 STATE EMISSIONS 20" NICKEL PAINTED ALUM WHLS ACTIVE COMFORT PACKAGE .REMOTE START SYSTEM .LED FOG LAMPS	INTERIOR • 12.3" LCD DIGITAL CLUSTER • 1TOUCH UP/DOWN DR/PASS WIN • 3RD ROW - 50/50 FOLD FLAT • DUAL ILLUM VIS VANITY MIRR		\$41,855.00	<ul> <li>A.B. B. B.</li></ul>
UNIVERSAL GARAGE DOOR OPENEF HEATED STEERING WHEEL LED SIGNATURE LIGHTING 8-WAY POWER PASSENGER SEAT FRONT LICENSE PLATE BRACKET	NO CHARGE			Frontal CrashDriver PassengerNot Rat Not RatBased on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size arSide CrashFront seat Rear seatBased on the risk of injury in a side impact.Based on the risk of injury in a side impact.RolloverBased on the risk of rollover in a single-vehicle crash.Star ratings range from 1 to 5 stars (*****), with Source: National Highway Traffic Safety Administ www.safercar.gov or 1-888-327-42
	RAMP ONE CA2H RAMP TWO	CONVOY	MSRP \$48,395.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	IFMUK8DH8SGB01562         WARNING: Operating, servicing and maintaining a pass         vehicle can expose you to chemicals including engine explanation         lead, which are known to the State of California to cause cancer
	State and Local taxes are not	Gasoline, License, and Title Fees,	RB 2X 545 006076 11 13 24	Iead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

1202411213362

