KTP-002496 SC 9-	-NORMAL,NB,102496,SD291	9112	CERI	CERTCERT TRD RAN		BOOKEXFLROTAE	BATT	029 1556/3
	UPER DU	ΤΥ	S	■ D 358	60	California	Air Resourc	es Board
ford.com	2025 F250 SRW 4X2 CRI XL 160" WB STYLESIDE 6.8L DEVCT NA PFI V8 E 10-SPEED AUTO TORQS	NGINE INT	TERIOR OXFORD WHITE TERIOR MEDIUM DARK SLA	TE VINYL			Enviro	comparable t
		FUNCTIONAL	S	AFETY/SECURITY		F	For information on I	now to compa
DOOR HANDLES - BLACK HEADLAMPS - AUTOLAMP (ON/OFF)	4.2" PRODUCTIVITY SCREEN AIR COND, MANUAL FRONT CLOTH SUN VISORS DRIVER SEAT-MANUAL LUMBA		K BRAKE SYS • / NECT 5GWI-FI • / TICS MODEM •	GWI-FI DDEM • AIRBAGS - SAFETY CANOPY® • BELT-MINDER CHIME • DRIVER/PASSENGER AIR BAGS • SECURE PKG 1 YR INCLUDED • SECURILOCK® ANTI-THEFT SYS • SOS POST-CRASH ALERT SYS™		Prote	ect the enviror	iment. Cho
• TRAILER SWAY CONTROL • TRAILER TOW MIRRORS • WIPERS- INTERMITTENT	OUTSIDE TEMP DISPLAY PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING:TILT/TELESCOPE,	REAR VIEW CAME REMOTE KEYLESS	A ENTRY EEN			Greenhouse Gas Rating (tailpipe only		
	CRUISE & AUDIO CONTROLS	FRT SUSPENSION V	W/STAB BAR W	ARRANTY 3YR/36,000 BUMPER / E 5YR/60,000 POWERTRA 5YR/60,000 ROADSIDE / 5YR/100,000 DIESEL EN	IN ASSIST	A+ Cleaner		D
INCLUDED ON THIS VEHICLE	(MSRP)				(MSRP)		ns are a primary cont sources Board based	
OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.600A 10-SPEED AUTO TORQSHIFT-G 3.73 RATIO NON LTD SLIP AXLE	O CHARGE O CHARGE O CHARGE	2	PRICE INFORMAT BASE PRICE TOTAL OPTIONS/OT TOTAL VEHICLE & C	HER	\$49,090.00 975.00 50,065.00			
SPARE TIRE AND WHEEL NO TRAILER BRAKE CONTROLLER JACK DROP-IN BEDLINER	O CHARGE O CHARGE 300.00	DESTINATION & DE	DELIVERY 2,095.00		GOVERNMENT 5-STAR SAFETY F Overall Vehicle Score Not Rate Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size and			
XL CHROME PACKAGE .FOG LAMPS						Frontal Crash Based on the risk Should ONLY be c	Driver Passenger of injury in a frontal impac compared to other vehicles	Not Rate Not Rate
						Side Crash Based on the risk	Front seat Rear seat of injury in a side impact.	Not Rate Not Rate
						Rollover		Not Rate
						Star ratings rang	of rollover in a single-vehi le from 1 to 5 stars (* onal Highway Traffic www.safercar.gov o	★★★★), with Safety Administ
	RAMP ONE RA4F		TOTAL MS	RP \$52,16	60.00			SED35860
	RAMP TWO	RAIL	Wheth Ford vehicle	er you decide to lease or e, you'll find the choices t	r finance your			
		ITEM #: 21-7500 O/T 60		s you a find the choices a See your dealer for det ord.com/finance.	ails or visit	vehicle can e	Dperating, servicing and m expose you to chemicals in wn to the State of Californi	cluding engine exh
	Information Disclosure State and Local taxes a			SPECIAL ORDER RB 2X 530 002496 04 29 25		To minimize exposu vehicle in a well-ven	re, avoid breathing exhaus tilated area and wear glov n go to www.P65Warnings	st, do not idle the ei es or wash your ha

