KTP-001638 FL	9-NORMAL,NB,101638,SD231	4056		RD RAMPBUMPCAM	PBOOKEXFLROTABA	TT	02 1031/	
	SUPER DU			9892	California	Air Resourc	es Boarc	
XL 176" WB STYLESIDE OXF 6.8L DEVCT NA PFI V8 ENGINE INTERIO			FORD WHITE		Environmen			
STANDARD EQUIPMENT INCLUDED A	AT NO EXTRA CHARGE					is are not directly r information on h	•	
EXTERIOR • DOOR HANDLES - BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • TOW HOOKS	INTERIOR • 4.2" PRODUCTIVITY SCREEN • AIR COND, MANUAL FRONT • CLOTH SUN VISORS • DRIVER SEAT-MANUAL LUMBAF	FUNCTIONAL • 4-WHEEL ANTILOCK • FORDPASS™ CONNI HOTSPOT TELEMATI • HILL START ASSIST	BRAKE SYS • ADVANCETRAC ^T ECT 5GWI-FI • AIRBAGS - SAFE CS MODEM • BELT-MINDER C	SAFETY/SECURITY • ADVANCETRAC™ WITH RSC® • AIRBAGS - SAFETY CANOPY® • BELT-MINDER CHIME • DRIVER/PASSENGER AIR BAGS • SECURE PKG 1 YR INCLUDED • SECURILOCK® ANTI-THEFT SYS • SOS POST-CRASH ALERT SYS™ WARRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 ROADSIDE ASSIST • SYR/100,000 DIESEL ENGINE		t the environ	ıment. Ch	
TRAILER SWAY CONTROL TRAILER TOW MIRRORS WIPERS- INTERMITTENT	OUTSIDE TEMP DISPLAY PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING:TILT/TELESCOPE,	REAR VIEW CAMERA REMOTE KEYLESS E SYNC®4 W/8" SCRE TWIN I-BEAM INDEP	SECURE PKG 1 SECURILOCK® SECURILOCK® SOS POST-CRASE			Greenhouse Gas Rating (tailpipe on		
	CRUISE & AUDIO CONTROLS	FRT SUSPENSION W	• 3YR/36,000 BUM • 5YR/60,000 POW • 5YR/60,000 ROA				D	
INCLUDED ON THIS VEHICLE	(MSRP)			(MSRP)		are a primary cont ources Board based		
OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.600A 10-SPEED AUTO TORQSHIFT-G	NO CHARGE		PRICE INFORMATION BASE PRICE TOTAL OPTIONS/OTHER	\$49,290.00 1,545.00				
3.73 ELECTRONIC-LOCKING AXLE FRONT LICENSE PLATE BRACKET 10000# GVWR PACKAGE 50 STATE EMISSIONS 120V/400W OUTLET SPARE TIRE AND WHEEL TRAILER BRAKE CONTROLLER JACK	430.00 NO CHARGE NO CHARGE 175.00 NO CHARGE 300.00	TOTAL VEHICLE & OPTIONS/OTHER DESTINATION & DELIVERY	50,835.00 2,095.00					
UPFITTER SWITCHES 250 AMP ALTERNATOR XL CHROME PACKAGE .FOG LAMPS	230.00 85.00 325.00				Frontal Crash Based on the risk of Should ONLY be cor	Driver Passenger injury in a frontal impace npared to other vehicles	Not Rate Not Rate t. s of similar size and	
				Side Crash Based on the risk of	Front seat Rear seat injury in a side impact.	Not Rate Not Rate		
						rollover in a single-vehic		
						from 1 to 5 stars (★ nal Highway Traffic www.safercar.gov c	Safety Adminis	
	RAMP ONE CH29			2,930.00			(SED29892	
	RAMP TWO	CONVOY TEM #: 24-F319 O/T 60	Ford Credit www.ford.com/finance	choices that are right r for details or visit	vehicle can exp	erating, servicing and m pose you to chemicals in to the State of Californi	Icluding engine exh	
	Information Disclosure A State and Local taxes are	ant to the Federal Automobile ct. Gasoline, License, and Title Fees, not included. Dealer installed e not included unless listed above.	SPECIAL ORI SD231 N RB 2X 525 001638	DER	To minimize exposure vehicle in a well-ventil	, avoid breathing exhaus ated area and wear glov go to www.P65Warnings	st, do not idle the e ves or wash your h	

