KTP-001747 _{FL}	9-NORMAL,NB,201747,SE012 98	70	CERTCERTCERT TRD	RAMPBUMPCAM	PBOOKEXFLROTABA	TT	1344,
	CLE DESCRIPTION SUPER DUT 2025 F250 SRW 4X2 SUPERCA XL 164" WB STYLESIDE 6.8L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT-G	B EXTERIO OXFO INTERIOF	RD WHITE	238	California	Air Resource Enviror	
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DOOR HANDLES - BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • TOW HOOKS • TRAILER SWAY CONTROL • TRAILER TOW MIRRORS • WIPERS- INTERMITTENT	AT NO EXTRA CHARGE INTERIOR • 4.2" PRODUCTIVITY SCREEN • AIR COND, MANUAL FRONT • CLOTH SUN VISORS • DRIVER SEAT-MANUAL LUMBAR • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS	EUNCTIONAL • 4-WHEEL ANTILOCK BRAM • FORDPASS™ CONNECT 5 HOTSPOT TELEMATICS MO • HILL START ASSIST • REAR VIEW CAMERA • REMOTE KEYLESS ENTRY • SYNC®4 W/8" SCREEN • TWIN I-BEAM INDEPENDE FRT SUSPENSION W/STAE	GWI-FI ODEM • BELT-MINDER CHIM • DRIVER/PASSENGE • SECURE PKG 1 YR I • SECURILOCK PASS • SOS POST-CRASH A	CANOPY® //E IR AIR BAGS INCLUDED ANTI THEFT ALERT SYS™ R / BUMPER TRAIN	Fo	is are not directly or r information on h at the environing se Gas Ratin g	ow to comp ment. Ch
INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.600A 10-SPEED AUTO TORQSHIFT-G 3.73 ELECTRONIC-LOCKING AXLE FRONT LICENSE PLATE BRACKET 1000# GVWR PACKAGE 50 STATE EMISSIONS 120V/400W OUTLET SPARE TIRE AND WHEEL TRAILER BRAKE CONTROLLER JACK 250 AMP ALTERNATOR XL CHROME PACKAGE .FOG LAMPS	NO CHARGE 430.00 NO CHARGE 175.00 NO CHARGE		• 5YR/100,000 DIESEL	- ENGINE (MSRP) \$47,835.00 1,315.00 49,150.00 2,095.00	Vehicle emissions are a primary contributor to clim California Air Resources Board based on this vehic GOVERNMENT 5-STAR SAFETY Overall Vehicle Score Not Rat Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size and		
	300.00 85.00 325.00				npared to other vehicles Driver Passenger injury in a frontal impact. mpared to other vehicles Front seat Rear seat injury in a side impact.	Not Rat Not Rat	
	RAMP ONE RH12 RAMP TWO	RAIL	OTAL MSRP \$51, Whether you decide to leas vehicle, you'll find the choid d Credit for you. See your dealer for www.ford.com/finance.	ces that are right	Star ratings range Source: Nation	rollover in a single-vehicl from 1 to 5 stars (★) nal Highway Traffic S www.safercar.gov of 1FT7X2AA0S rerating, servicing and ma pose you to chemicals inc to the State of California	le crash. ★ ★ ★ ★), wit Safety Adminis r 1-888-327-42 SED41238 Mathing a passe
	This label is affixed pursuant to t Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not in	oline, License, and Title Fees, luded. Dealer installed S	SPECIAL ORDE E012 N RB 2X 530 001747 05		To minimize exposure vehicle in a well-ventil	, avoid breathing exhaust ated area and wear glove go to www.P65Warnings.	, do not idle the e s or wash your h

