RTT-000705 AL 9-NORM	AL,NB,103785,SD291 IU.		рыкірыкірі	ERT  TRD  RAMPBUMP CAMI	PBOOKEXFLROTABATTI 3015/3
Cord 202 XLT 7.3	PER DUTY 5 F250 SRW 4X4 CREW CAE 160" WB STYLESIDE L DEVCT NA PFI V8 ENGINE SPEED AUTO TORQSHIFT	BEXTERIO AVAL/ INTERIOI		<b>59006</b>	California Air Resources Board Environment
HEADLAMPS - AUTOLAMP     AIR CO (ON/OFF)     CLOT     TOW HOOKS     CLTH     TRAILER BRAKE CONTROLLER     TRAILER SWAY CONTROL     TRAILER TOW MIRRORS     POWE     STEEF     CRUIS	OR	FUNCTIONAL • FORDPASS™ CONNECT 5 HOTSPOT TELEMATICS M • HILL START ASSIST • MONO BEAM COIL SPRIN SUSPENSION W/STAB BAI • PRE-COLLISION ASSIST V • REAR VIEW CAMERA • REMOTE KEYLESS ENTRY • SYNC®4	ODEM G FRT AIRBAGS BELT-MIN G FRT C DRIVER/F SECURE SOS POS WARRANT - 3YR/36,00 - 5YR/60,00	ETRAC™ WITH RSC® 5 - SAFETY CANOPY® NDER CHIME PASSENGER AIR BAGS PKG 1 YR INCLUDED T-CRASH ALERT SYS™	These ratings are not directly comparable to For information on how to comparable Protect the environment. Cho Greenhouse Gas Rating (tailpipe on the A+ Cleaner
SPARE TIRE AND WHEEL NO CHAI ROOF CLEARANCE LIGHTS 9 JACK REMOTE START SYSTEM 25 CLOTH 40/CONSOLE/40 SEAT 30 DEALER INSTALLED OPTIONS	0.00 RGE RGE 0.00	BA: TO	ICE INFORMATION SE PRICE TAL OPTIONS/OTHER TAL VEHICLE & OPTIONS/ STINATION & DELIVERY	(MSRP) \$55,700.00 6,775.00 OTHER 62,475.00 2,095.00	Vehicle emissions are a primary contributor to clima California Air Resources Board based on this vehicle
	RAMP ONE CA3J RAMP TWO ITEM #:	CONVOY	Ford vehicle you'll fi	\$64,570.00 ecide to lease or finance your nd the choices that are right ir dealer for details or visit finance.	IFT8W2BN2SED59006         WARNING: Operating, servicing and maintaining a passer vehicle can expose you to chemicals including engine exh lead, which are known to the State of California to cause cancer at the state of Califor
	This label is affixed pursuant to the Information Disclosure Act. Gaso State and Local taxes are not inclu- options or accessories are not inc	e Federal Automobile line, License, and Title Fees, ıded. Dealer installed S	D291 N RB 2X 530 0		To minimize exposure, avoid breathing exhaust, do not idle the er vehicle in a well-ventilated area and wear gloves or wash your ha For more information go to www.P65Warnings.ca.gov/passenger-

