KIP-001858 OR	9-NORMAL,NB,001858,SC061 <b>178</b>	۲/ 	CERT CERT CERT TRD RAMP BUMP	CAMPBOOKEXFLROTA 576/
	SUPER DUTY 2025 F450 DRW 4X4 CREW CAB PLATINUM 176" WB STYLESIDE 6.7 HI OUTPUT POWER STROKE 10-SPEED AUTO TORQSHIFT	EXTERIOR CARBONIZED INTERIOR	SE C80305 O GRAY 2 PLAT BLUE LEATHE	California Air Resources Board Environmen
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • LED FOG LAMPS • PICKUP BOX TIE DOWN HOOKS • POWER SLIDING REAR WINDOW W/DEFROST & PRIVACY TINT • POWER TAILGATE • POWER TAILGATE • POWERSCOPE TT POWER-FOLD MIRRORS, POWER/HEATED • PROJECTOR HEADLAMPS LED • TAIL LAMPS - LED • TAILGATE STEP • TOW HOOKS • TRAILER BRAKE CONTROLLER • WIPERS - RAIN-SENSING INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.773A 6.7 HI OUTPUT POWER STROKE 10-SPEED AUTO TORQSHIFT FRONT LICENSE PLATE BRACKET FX4 OFF-ROAD PACKAGE SKID PLATES 14000# GVWR PACKAGE ENGINE BLOCK HEATER 50 STATE EMISSIONS PRO POWER ONBOARD - 2KW JACK WHEEL WELL LINERS - FRONT MOONROOF POWER-TWIN PANEL EXTERIOR BACKUP ALARM TOUGH BED SPRAY IN BEDLINER	In the second state of the		<ul> <li>BELT-MINDER CHIME</li> <li>DRIVER/PASSENGER AIR BAGS</li> <li>LED CTR HIGH MNT STOP LAMP</li> <li>SECURE PKG 1 YR INCLUDED</li> <li>SOS POST-CRASH ALERT SYS™</li> <li>MERANTY</li> <li>3YR/36,000 BUMPER / BUMPER</li> <li>5YR/60,000 POWERTRAIN</li> <li>5YR/60,000 DIESEL ENGINE</li> </ul> (MSRP) PRMATION \$94,035.00	
		RAIL 4-B02R O/T 1 Ford Credit	MSRP \$103,345.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine exh lead, which are known to the State of California to cause cancer
	This label is affixed pursuant to the Information Disclosure Act. Gasolin State and Local taxes are not incluc options or accessories are not incl	ne, License, and Title Fees, led. Dealer installed SC061 N	<b>SPECIAL ORDER</b> RB 2X 525 001858 03 06 25	To minimize exposure, avoid breathing exhaust, do not idle the er vehicle in a well-ventilated area and wear gloves or wash your ha For more information go to www.P65Warnings.ca.gov/passenger-

