ULC บ พ С

| KIP-001794 <sub>FL</sub>  | 9-NORMAL,NB,101794,RB291 40   | )32  | CERT CERT CERT TRD RAMP BUMP C   | CAMPBOOKEXFLROTA 635/1  |
|---|---|--|--|---|
|   | SUPER DUT   | Υ  | <sup>RE</sup> D10409   | California Air Resources Board  |
| ford.com  | 2024 F250 SRW 4X2 REG CAI<br>XL 142" WB STYLESIDE<br>6.8L DEVCT NA PFI V8 ENGIN<br>10-SPEED AUTO TORQSHIFT-   | BEXTERIOR<br>OXFORD WH<br>EINTERIOR  | ITE<br>RK SLATE VINYL  | Environment<br>These ratings are not directly comparable t  |
| EXTERIOR<br>• DOOR HANDLES - BLACK<br>• HEADLAMPS - AUTOLAMP<br>(ON/OFF)<br>• TOW HOOKS<br>• TRAILER BRAKE CONTROLLER<br>• TRAILER SWAY CONTROL<br>• TRAILER TOW MIRRORS<br>• WIPERS- INTERMITTENT  | <ul> <li>HTERIOR</li> <li>4.2" PRODUCTIVITY SCREEN</li> <li>AIR COND, MANUAL FRONT</li> <li>CLOTH SUN VISORS</li> <li>DRIVER SEAT-MANUAL LUMBAR</li> <li>OUTSIDE TEMP DISPLAY</li> <li>PARTICULATE AIR FILTER</li> <li>POWER LOCKS AND WINDOWS</li> <li>STEERING:TILT/TELESCOPE,<br/>CRUISE &amp; AUDIO CONTROLS</li> </ul>   | <ul> <li>FUNCTIONAL</li> <li>4-WHEEL ANTILOCK BRAKE SYS</li> <li>FORDPASS™ CONNECT 5GWI-FI<br/>HOTSPOT TELEMATICS MODEM</li> <li>HILL START ASSIST</li> <li>REAR VIEW CAMERA</li> <li>REMOTE KEYLESS ENTRY</li> <li>SYNC®4 W/8" SCREEN</li> <li>TWIN I-BEAM INDEPENDENT<br/>FRT SUSPENSION W/STAB BAR</li> </ul> | <ul> <li>SAFETY/SECURITY</li> <li>ADVANCETRAC™ WITH RSC®</li> <li>AIRBAGS - SAFETY CANOPY®</li> <li>BELT-MINDER CHIME</li> <li>DRIVER/PASSENGER AIR BAGS</li> <li>SECURILOCK® ANTI-THEFT SYS</li> <li>SOS POST-CRASH ALERT SYS™</li> <li>MARRANTY</li> <li>SYR/36,000 BUMPER / BUMPER</li> <li>SYR/60,000 DIESEL ENGINE</li> <li>SYR/60,000 ROADSIDE ASSIST</li> </ul> | For information on how to compare<br>Protect the environment. Cho<br>Greenhouse Gas Rating (tailpipe onl<br>A+<br>Cleaner<br>Using alternative  |
| INCLUDED ON THIS VEHICLE         OPTIONAL EQUIPMENT PKG.600A         10-SPEED AUTO TORQSHIFT-G         3.73 RATIO REGULAR AXLE         10000# GVWR PACKAGE         50 STATE EMISSIONS         SPARE TIRE AND WHEEL         JACK         250 AMP ALTERNATOR         HEAVY SERVICE FRONT SUSPENSION | (MSRP)<br>NO CHARGE<br>NO CHARGE<br>NO CHARGE<br>85.00<br>125.00  | TOTAL VEHI   |  | Vehicle emissions are a primary contributor to clima         California Air Resources Board based on this vehicle         GOVERNMENT 5-STAR SAFETY F         Overall Vehicle Score       Not Rate         Based on the combined ratings of frontal, side and rollover.         Should ONLY be compared to other vehicles of similar size and         Frontal       Driver         Passenger       Not Rate         Based on the risk of injury in a frontal impact.         Should ONLY be compared to other vehicles of similar size and         Side       Front seat         Crash       Rear seat         Based on the risk of injury in a side impact.         Should ONLY be compared to other vehicles of similar size and         Not Rate         Based on the risk of injury in a frontal impact.         Should ONLY be compared to other vehicles of similar size and         Not Rate         Based on the risk of injury in a side impact.         Based on the risk of injury in a side impact.         Rollover       Not Rate         Based on the risk of rollover in a single-vehicle crash.         Star ratings range from 1 to 5 stars (* * * * *), with         Source: National Highway Traffic Safety Administ |
|   | RAMP ONE<br>CA21  | ΤΟΤΑΙ  | LMSRP \$47,175.00  | www.safercar.gov or 1-888-327-423<br>1FTBF2AA1RED10409  |
|   | RAMP TWO       ITEM 4         This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not in options or accessories are not in options options or accessories are not in options | 24-Z521 O/T 2 Ford Credit<br>o the Federal Automobile<br>asoline, License, and Title Fees,<br>included. Dealer installed RB291 N   | Whether you decide to lease or finance your<br>vehicle, you'll find the choices that are right<br>for you. See your dealer for details or visit<br>www.ford.com/finance.<br>RB 2X 425 001794 02 29 24  | WARNING: Operating, servicing and maintaining a passer<br>vehicle can expose you to chemicals including engine exh<br>lead, which are known to the State of California to cause cancer a<br>To minimize exposure, avoid breathing exhaust, do not idle the en<br>vehicle in a well-ventilated area and wear gloves or wash your ha<br>For more information go to www.P65Warnings.ca.gov/passenger   |

