KTP-000296 _{CA}	72V 436 6B 2 X LABL ADJ COV PRCS B	16 RAMP BUMP	REC83565 SUPER	MAIL	02: 554
	CLE DESCRIPTION SUPER DUTY 2024 F250 SRW 4X4 REG CAB XL 142" WB STYLESIDE 6.8L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT-G	EXTERIOR OXFORD WHI INTERIOR	RE C83565 TE RK SLATE VINYL		sources Board
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • DOOR HANDLES - BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER TOW MIRRORS	INTERIOR • 4.2" PRODUCTIVITY SCREEN • AIR COND, MANUAL FRONT • CLOTH SUN VISORS • DRIVER SEAT-MANUAL LUMBAR • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS	FUNCTIONAL • 4-WHEEL ANTILOCK BRAKE SYS • FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM • HILL START ASSIST • MANUAL LOCKING HUBS • MONO BEAM COIL SPRING FRT SUSPENSION W/STAB BAR	SAFETY/SECURITY • ADVANCETRAC [™] WITH RSC® • AIRBAGS - SAFETY CANOPY® • BELT-MINDER CHIME • DRIVER/PASSENGER AIR BAGS • SECURILOCK® ANTI-THEFT SYS • SOS POST-CRASH ALERT SYS [™]	For informa	t directly comparable t ation on how to compa environment. Cho Rating (tailpipe onl
• WIPERS- INTERMITTENT	• STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS	• REAR VIEW CAMERA • REMOTE KEYLESS ENTRY • SYNC®4 W/8" SCREEN	WARRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSIST • 5YR/100,000 DIESEL ENGINE (MSRI	P)	
OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.600A 10-SPEED AUTO TORQSHIFT-G 3.73 ELECTRONIC-LOCKING AXLE FRONT LICENSE PLATE BRACKET 10000# GVWR PACKAGE 50 STATE EMISSIONS 120V/400W OUTLET SNOWPLOW PREP/CAMPER PACKAGE SPARE TIRE AND WHEEL JACK UPFITTER SWITCHES 250 AMP ALTERNATOR XL CHROME PACKAGE .FOG LAMPS	NO CHARGE 430.00 NO CHARGE TOTAL VEHIC		\$47,760.0	GOVERNMEN Overall Vehicle Scor Based on the combined ratings Should ONLY be compared to of Frontal Driver Crash Passe	of frontal, side and rollover. ther vehicles of similar size and Not Rate Not Rate
				Based on the risk of injury in a fr Should ONLY be compared to of Side Front s Crash Rear s Based on the risk of injury in a s Rollover Based on the risk of rollover in a Star ratings range from 1 to Source: National Highwa www.safe	seat Not Rate seat Not Rate ide impact. Not Rate
	RAMP ONE RA84 RAMP TWO	RAIL TOTAL	MSRP \$51,140.00 Whether you decide to lease or finance you vehicle, you'll find the choices that are right		TBF2BA1REC83565
	This label is affixed pursuant to the Information Disclosure Act. Gasol State and Local taxes are not inclu options or accessories are not inclu	r2-2366 O/T 59 Ford Credit e Federal Automobile ine, License, and Title Fees, ded. Dealer installed R860 R	for you. See your dealer for details or visit www.ford.com/finance. SPECIAL ORDER 6B 2X 425 000296 01 29 24	WARNING: Operating, service vehicle can expose you to on lead, which are known to the State To minimize exposure, avoid breat vehicle in a well-ventilated area are For more information go to www.P	thing exhaust, do not idle the e

05/17/2024

