

EXTERIOR
OXFORD WHITE
INTERIOR
DARK PALAZZO GRAY VINYL

- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

INCLUDED ON THIS VEHICLE		(MSRP)	PRICE INFORMATION		(MSRP)
OPTIONAL EQUIPMENT/OTHER			PRICE INFORMATION		
PREFERRED EQUIPMENT PKG.101A			BASE PRICE		\$47,255.00
3.73 LIMITED SLIP AXLE		325.00	TOTAL OPTIONS/OTHER		1,475.00
FRONT LICENSE PLATE BRACKET	NO CHARGE				
VINYL F/R FLOOR COVERING		245.00			
AUTO START STOP REMOVAL	-	50.00	TOTAL VEHICLE & OPTIONS/OTHER		48,730.00
WIFI 4G LTE HOTSPOT DELETE	-	20.00	DESTINATION & DELIVERY		1,895.00
9070# GVWR PACKAGE	NO CHARGE				
50 STATE EMISSIONS	NO CHARGE				
REVERSE SENSING SYSTEM		295.00			
RADIO - SYNC3, 4" SCN		280.00			
CRUISE CONTROL		325.00			
2 ADDITIONAL KEYS		75.00			
E-85 FLEX FUEL CAPABLE	NO CHARGE				



Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.

Using alternative fuels may change scores.

Vehicle emissions are a primary contributor to climate change and smog. Ratings are determined by the California Air Resources Board based on this vehicle's measured emissions.



Based on the combined ratings of frontal, side and rollover.
Should ONLY be compared to other vehicles of similar size and weight.


Based on the risk of injury in a frontal impact.
Should ONLY be compared to other vehicles of similar size and weight.

Based on the risk of injury in a side impact.

Based on the risk of rollover in a single-vehicle crash.

Star ratings range from 1 to 5 stars (★★★★★), with 5 being the highest.
Source: National Highway Traffic Safety Administration (NHTSA).
www.safercar.gov or 1-888-327-4236

1FTBR1C84PKC07043

 **WARNING:** Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

SCAN OR TEXT 1FPKC07043 TO 48028

Msg & Data rates may apply.
Text HELP for help



www.ford.com/help/privacy-terms/