
| VEH  | ICLE DESCRIPTION   |   | <sup>sк</sup> А19   | 660  | California Air Re  | sources Boar   |
|--|--|---|---|--|--|--|
| ford.com   | 2025 350 HR CARGO RWD<br>148" WHEELBASE<br>3.5L ECOBOOST V6 (GAS)<br>10-SPEED TRANSMISSION   |   | EXTERIOR<br>OXFORD WHITE<br>INTERIOR<br>DARK PALAZZO GRAY CLOTH       |  | Environmen   |  |
| STANDARD EQUIPMENT <u>INCLUDED #</u>   | AT NO EXTRA CHARGE   |   |   |  | These ratings are not<br>For informa   | t directly comparable<br>ation on how to comp  |
| EXTERIOR<br>• AUXILIARY FUEL PORT<br>• BODY SIDE MOLDINGS - BLACK<br>• BUMPERS - CARBON BLACK<br>• FULL SIZE SPARE TIRE/WHEEL  | INTERIOR<br>• AIR CONDITIONING<br>• ASSIST HANDLES - A-PILLAR<br>• CENTER CONSOLE<br>• INTERIOR LIGHTING - LED                                   | FUNCTIONAL<br>• AUTO HIGH-BEAM HEADLA<br>• ELECTRONIC PWR ASST S<br>• FORWARD COLLISION WA<br>• HILL START ASSIST | TEER<br>• ADVANCETRAC™ M<br>• AIRBAGS ⊠ FRONT,<br>SAFETY CANOPY® 5    | ITH RSC®<br>SIDE AND<br>SYSTEM   |  | environment. Ch  |
| • HEADLAMP COURTESY DELAY<br>• WIPERS - RAIN-SENSING   | LOCKING GLOVE BOX     POWERPOINT - 12V (FRONT)     STEERING - TILT/TELESCOPIC     TACHOMETER   | LANE-KEEPING SYSTEM     POST-COLLISION BRAKING     PRE-COLLISION ASSIST W/AEB     REAR VIEW CAMERA                | G • SECURILOCK® ANT<br>/AEB • SOS POST-CRASH /                        | <ul> <li>BRAKES - 4WHEEL DISC W/ABS</li> <li>SECURILOCK® ANTI-THEFT SYS</li> <li>SOS POST-CRASH ALERT SYS™</li> <li>TIRE PRESSURE MONIT SYS</li> </ul> | Greenhouse Gas   | Rating (tailpipe or  |
|  |  | W/ TRAILER HITCH ASSIST<br>• SELECTABLE DRIVE MODE<br>• SIDE-WIND STABILIZATION                                   | S <u>WARRANTY</u>   | R / BUMPER<br>FRAIN  | A+<br>Cleaner  | D  |
|  |  |   |   | (11077)  | Vehicle emissions are a prin<br>California Air Resources Boa   |  |
| INCLUDED ON THIS VEHICLE<br>OPTIONAL EQUIPMENT/OTHER<br>PREFERRED EQUIPMENT PKG.101A<br>3.5L ECOBOOST V6 (GAS)   | (MSRP)<br>2,700.00   | BAS   | CE INFORMATION<br>E PRICE<br>AL OPTIONS/OTHER                         | (MSRP)<br>\$54,200.00<br>5,125.00  |  |  |
| 3.73 NON-LIMITED SLIP AXLE<br>FRONT LICENSE PLATE BRACKET<br>TIE DOWN CARGO HOOKS<br>9500# GVWR PACKAGE<br>2WAY DRV/PASS PALAZZO CLOTH<br>50 STATE EMISSIONS<br>REVERSE SENSING SYSTEM<br>HD TRAILER TOW PACKAGE<br>RADIO - SYNC3, 4" SCN<br>SRW - STEEL W/ SILVER COVER<br>EXTENDED FUEL TANK (31 GAL)<br>FRONT OVERHEAD SHELF<br>TRAILER BRAKE CONTROLLER<br>LARGE CENTER CONSOLE<br>HEAVY-DUTY SCUFF PLATE KIT<br>2 ADDITIONAL KEYS | DES<br>25.00<br>NO CHARGE<br>115.00<br>NO CHARGE<br>295.00   |   | AL VEHICLE & OPTIONS/OTHER 59,325.00<br>STINATION & DELIVERY 2,095.00 | GOVERNMENT<br>Overall Vehicle Scor<br>Based on the combined ratings of<br>Should ONLY be compared to oth   |  |  |
|  | 485.00<br>280.00<br>35.00<br>285.00<br>75.00<br>405.00<br>NO CHARGE<br>350.00  |   |   |  | FrontalDriverCrashPasselBased on the risk of injury in a fro<br>Should ONLY be compared to otto                | nger \star ★   |
|  | 75.00  |   |   |  | SideFront sCrashRear sBased on the risk of injury in a single  | seat Not Ra  |
|  |  |   |   |  | <b>Rollover</b><br>Based on the risk of rollover in a  | Not Rat single-vehicle crash.  |
|  |  |   |   |  | Star ratings range from 1 to 5<br>Source: National Highwa<br>www.safe  |  |
|  | RAMP ONE<br>CM1P   | т   |   | 420.00   |  | TBW3XGXSKA19660  |
|  | RAMP TWO   | CONVOY  | Whether you decide to lease vehicle, you'll find the choir            | es that are right  | WARNING: Operating, serv   | vicing and maintaining a pass  |
|  |  |   | Credit for you. See your dealer for www.ford.com/finance.             | aetails or visit   | vehicle can expose you to c lead, which are known to the State   | chemicals including engine ex<br>e of California to cause cance                          |
|  | This label is affixed pursuant to t<br>Information Disclosure Act. Gas<br>State and Local taxes are not inc<br>options or accessories are not in | oline, License, and Title Fees,<br>luded. Dealer installed SI   | SB241 N RB 2X 525 004709 02 24 25                                     |  | To minimize exposure, avoid breat<br>vehicle in a well-ventilated area an<br>For more information go to www.Pf | hing exhaust, do not idle the<br>d wear gloves or wash your<br>65Warnings.ca.gov/basseng |

1202503047531



he engine except as necessary, service your ur hands frequently when servicing your vehicle. nger-vehicle

for help

www.ford.com/help/privacy-terms/