KAN-003760 <sub>FL</sub>	9-NORMAL, NB, 203760, PL28	2 <b>14440</b> 220231206	1622 ULC CERTICERT			018452 1816/3692
VEHI	CLE DESCRIPTION ELEND   2023 F-150 4X2 SUPERCREW EXTING   145" WHEELBASE IO   2.7L V6 ECOBOOST INTE   ELEC TEN-SPEED AUTO W/TOW M B		AND AND AND AND AND AND AND AND		Provide a construction of the second seco	
<b>OPTIONAL EQUIPMENT/OTHER</b> 2.7L V6 ECOBOOST 3.55 RATIO REGULAR AXLE 6400# GVWR PACKAGE FRONT LICENSE PLATE BRACKET 50 STATE EMISSIONS ONBOARD 400W OUTLET INTERIOR WORK SURFACE CLASS IV TRAILER HITCH MIRROR MAN FOLD W/POWER GLASS SIRIUS XM W/ 360L XLT SPORT APPEARANCE PACKAGE .265/60R18 BSW ALL-SEASON .18" 6-SPOKE GLOSS BLACK WHEEL	1,285.00 NO CHARGE NO CHARGE 195.00 465.00		TOTAL BEFORE DISCOUNT XLT HIGH CHRM OR SPRT TOTAL SAVINGS	TS 56,255.00	Overall Vehicle ScoreBased on the combined ratings of fr Should ONLY be compared to otherFrontal CrashDriver PassengBased on the risk of injury in a front. Should ONLY be compared to otherSide CrashFront sea Rear seaBased on the risk of injury in a sideSide CrashRear sea Rear seaBased on the risk of injury in a sideSide CrashFront sea Rear seaBased on the risk of injury in a sideStar ratings range from 1 to 5 s Source: National Highway	$\begin{array}{c} & & & & & & & & & & & & & & & & & & &$
	RAMP ONE		TOTAL MSRP	\$54,255.00	1ETE	W1CP8PKG12030
	CA21 RAMP TWO	CONVOY ITEM #: 24-9278 O/T 2 ITEN to the Federal Automobile	Whether you decide vehicle, you'll find t Ford Credit www.ford.com/fina	e to lease or finance your the choices that are right ealer for details or visit ance.	WARNING: Operating, servicing and maintaining a passenger vehic vehicle can expose you to chemicals including engine exhaust, carbulated, which are known to the State of California to cause cancer and birth d	
	Information Disclosur State and Local taxes	irsuant to the Federal Automobile e Act. Gasoline, License, and Title Fees, are not included. Dealer installed s are not included unless listed above.	PL282 N RB 2X 370 003760 11 28 23		To minimize exposure, avoid breathing exhaust, do not idle the engine excervehicle in a well-ventilated area and wear gloves or wash your hands freque For more information go to www.P65Warnings.ca.gov/passenger-vehicle.	

2202312061622

05/01/2024

