
FD

	LE DESCRIPTION - 150 2025 F-150 4X4 SUPERCREW 145" WHEELBASE 2.7L V6 ECOBOOST ELEC TEN-SPEED AUTO TRANS	O INTE	SF ERIOR XFORD WHITE RIOR LACK STX CLOTH 4	A24199	EPA DOT Fuel Economy and En Fuel Economy MPG MPGe. MPGe.
STANDARD EQUIPMENT INCLUDED AT EXTERIOR • DAYTIME RUNNING LAMPS • AASY FUEL® CAPLESS FILLER • FULLY BOXED STEEL FRAME • GRILLE - BLACK & DARK GRAY • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTO LAMP (DNOFF) • LED REFLECTOR HEADLAMPS • PICKUP BOX TIE DOWN HOOKS • TAILER SWAY CONTROL • WIPERS • INTERMITTENT • DICLUDED N THIS VEHICE EXTENDED RANGE 36GAL FUEL TAN • 275/60R20 BSW ALL-TERRAIN • 275/60R20 BSW ALL-TERRAIN • 275/00R20 BSW	NO EXTRA CHARGE PORT IN A CONTROL PORT IN A CONTR	EUNCTIONAL AM/FM STEREO AUTO HOLD BLIS W/CROSS-TRAI CLASS IV TRAILER H SMART TRLR TOW C CURVE CONTROL FORDPASS™ CONNI HOTSPOT TELEMATI LANE-KEEPING SYS POST-COLLISION ASS REVERSE SENSING A REAR VIEW CAMERA SELECTABLE DRIVE SYNC®4 W/EVR & 12	AE AII FFIC ALERT MC ITCH W/ ONNECTOR CT PE ECT 5GWI-FI CS MODEM TEM AKING SIST W/AEB AND SIST W/AEB AND SIST MODES SY MODES	ER \$51,130.00 2,005.00 TIONS/OTHER 53,135.00 /ERY 1,995.00 ISCOUNTS 55,130.00 NT - 2,000.00	fueleconomy.gov Calculate personalized estimates and compare vehicles GOVERNMENT 5-STAR SAFET Overall Vehicle Score Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size
	RAMP ONE CH29 RAMP TWO ITEM #: This label is affixed pursuant to the information Disclosure Act. Gas State and Local taxes are not incorptions or accessories are not incorptions ore accessories are not incorptions or accessories are n	24-Z801 O/T 2 the Federal Automobile soline, License, and Title Fees, sluded. Dealer installed	Ford Credit for you. www.for	RP \$52,130.00 Tyou decide to lease or finance your you'll find the choices that are right See your dealer for details or visit d.com/finance.	IFTEW2LP1SFA24199 WARNING: Operating, servicing and maintaining a part vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle th vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passen



2202412050817