W 9-NORMAL, NB, 003625, RC251 11899 220240405 4370 CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

FORD PERFORMANCE 2024 3.5L E	TION ORAPT RAPTOR 4X4 SUPERCR WHEELBASE COBOOST HIGH OUTPU TEN-SPEED AUTO TRA	EW EXT F UT INTI	RF ERIOR RAPID RED MET TINTED ERIOR RECARO BLACK SEAT	A69881	EPA DOT Fuel Economy and En Fuel Economy Standard P T MPG Standard P MPGe. MPGe.
• BUMPER - RAPTOR-UNIQUE • 2ND ROW • FRONT PERFORMANCE • A/C W/DI • DUAL EXHAUST SYSTEM W/DUAL • ADAPTIV TAILPIPES • COMPAS • FUEL TANK - 36.0 GALLON • HEAD-UF • HEADLAMPS - AUTO HIGH BEAM • HTD LTH • HEADLAMPS - AUTOLAMP • LEATHEF (ON/OFF) • OUTSIDE • LED PROJECTOR W/ DYNAMIC • PEDALS BENDING HEADLAMPS • POWER I • LED SIDE-MIRROR SPOTLIGHTS • RAPTOR • RIGID® LED FOG LAMP • RAPTOR • RUNNING BOARDS - CAST ALUM • STEERIN	DUCTIVITY SCREEN (HEATED SEATS JAL CLIMATE CONTROL E CRUISE CONTROL S DISPLAY R WRAPPED STR WHLEL TEMP DISPLAY PWR ADJ W/MEMORY OCKS AND WINDOWS BRANDED FLOOR MATS UNIQUE CENTER STACK G - TILT/TELESCOPIC (TH AUDIO	EUNCTIONAL 9 360-DEGREE CAME 9 B&O UNLEASHED, 1 9 EDD UTILITY PKG 9 FORDPASS™ CONN HOTSPOT TELEMAT 9 FOX LIVE VALVE SH 9 PRO TRAILER BACK 9 PRO TRAILER HITCH 9 REVERSE SENSING REAR VIEW CAMERA 9 SKID PLATES 9 SYNC®4 W/EVR & 1 1 TERRAIN MANAGEN 1 TRAIL CONTROL	RA • ADVA 4 SPKR • AIRBA MOUN IECT 5GWI-FI • AIRBA ICS MODEM • PERIN OCKS • SECU G • SOS F (UP ASSIST • STOLI + ASSIST • STOLI + ASSIST • TIRE F AND A 2" SCREEN • 5YR/6	6,000 BUMPER / BUMPER 0,000 POWERTRAIN 0,000 ROADSIDE ASSIST (MSRP) \$78,330.00 14,055.00 NS/OTHER 92,385.00	Image: A generation of the state of the
	RAMP ONE CA46				Source: National Highway Traffic Safety Admir www.safercar.gov or 1-888-327-4 1FTFW1RG4RFA69881
	RAMP TWO ITEM This label is affixed pursuant t Information Disclosure Act. G State and Local taxes are not i options or accessories are not	11-0001 O/T 1 to the Federal Automobile iasoline, License, and Title Fees, included. Dealer installed	Ford Credit for you www.ford.co	LORDER	WARNING: Operating, servicing and maintaining a pase vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle th vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passen

05/21/2024



2202404054370