FD

220250408 6500 BLEND

FORD PERFORMANCE	DESCRIPTION - 150 RAPTO 2025 RAPTOR 4X4 SUPERCREW 145" WHEELBASE 3.5L ECOBOOST HIGH OUTPUT ELEC TEN-SPEED AUTO TRANS			EPA DOT Fuel Economy and E Fuel Economy Standard MPG MPG
 5 LINK REAR SUSPENSION BUMPER - RAPTOR-UNIQUE FRONT PERFORMANCE DUAL EXHAUST SYSTEM W/DUAL TAILPIPES FUEL TANK - 36.0 GALLON HEADLAMPS - AUTO HIGH BEAM HEADLAMPS - AUTOLAMP (ON/OFF) LED PROJECTOR W/ DYNAMIC BENDING HEADLAMPS LED SIDE-MIRROR SPOTLIGHTS RIGID® LED FOG LAMP WHEEL LIP MOLDINGS INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 802A RAPTOR SERIES 17" CAST ALUM BEAD-LOCK CAPAB DUAL VALVE SHOCKS OPTIONAL EQUIPMENT/OTHER 37 X 12.5R17 BSW ALL-TERRAIN 4.10 ELECTRONIC LOCK RR AXLE Y400# GVWR PACKAGE 50 STATE EMISSIONS 	INTERIOR 12" PRODUCTIVITY SCREEN 2ND ROW HEATED SEATS 4/C W/DUAL CLIMATE CONTROL ADAPTIVE CRUISE CONTROL COMPASS HEAD-UP DISPLAY HTD LTHR WRAPPED STR WHL HTD/VENTILATED FRT SEATS OUTSIDE TEMP DISPLAY PEDALS-PWR ADJ W/MEMORY POWER LOCKS AND WINDOWS RAPTOR BRANDED FLOOR MATS RAPTOR-UNIQUE CENTER STACK STEERING - TILT/TELESCOPIC WHEEL WITH AUDIO MOCHARGE 1,495.00 NO CHARGE	 EUNCTIONAL a800-DEGREE CAMERA B800 UNLEASHED, 14 SPKR B800 UTILITY PKG FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM FOX LIVE VALVE SHOCKS MOBILE OFFICE PKG PRO TRAILER HITCH ASSIST REVERSE SENSING AND REAR VIEW CAMERA SKID PLATES SYNC®4 W/EVR & 12" SCREEN TERAIN MANAGEMENT SYSTEM TAIL CONTROL 	\$79,005.00 S/OTHER 12,965.00 E & OPTIONS/OTHER 91,970.00	Image: State of the risk of injury in a final single and other vehicles of similar single and other single and
	ITEM #:	Find Ve	MSRP \$93,965.00 Thether you decide to lease or finance your chicle, you'll find the choices that are right or you. See your dealer for details or visit ww.ford.com/finance.	IFTFW1RG4SFA97878
	This label is affixed pursuant to the Information Disclosure Act. Gasolin State and Local taxes are not incluc options or accessories are not incl	e Federal Automobile ine, License, and Title Fees, ded. Dealer installed SC311 N RI	ww.ford.com/finance. B 2X 555 003900 03 31 25	lead, which are known to the State of California to cause ca To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash ye For more information go to www.P65Warnings.ca.gov/pass



2202504086500