			^{ѕк} Е76	234	
F=150 2025 F-150 4X2 SUPERCREW 145" WHEELBASE 3.5L V6 ECOBOOST ELEC TEN-SPEED AUTO TRANS		EXTERIOR RAPID RED MET TINTED CC INTERIOR			Fuel Economy and En Fuel Economy MPG Standard Pi 87 MPG. Th MPGe.
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LED REFLECTOR HEADLAMPS • PICKUP BOX TIE DOWN HOOKS • POWER TAILGATE LOCK	T NO EXTRA CHARGE INTERIOR • 12" PRODUCTIVITY SCREEN • DOOR LOCKS - POWER • DUAL SUNVISORS • ILLUMINATED ENTRY • MESSAGE CTR: OUTSIDE TEMP, COMPASS, TRIP COMPUTER • TILT/TELESCOPE STR COLUMN	FUNCTIONAL • AUTO HOLD • BLIS W/CROSS-TRAFFIC AL • CLASS IV TRAILER HITCH W SMART TRLR TOW CONNEC • FORDPASS™ CONNECT 5G HOTSPOT TELEMATICS MO • LANE-KEEPING SYSTEM • POST-COLLISION BRAKING • PRE-COLLISION ASSIST W/	ER HITCH W/ MOUNTED SIDE IMPACT OW CONNECTOR • AIRBAGS - SAFETY CANON ONNECT 5GWI-FI • CTR HIGH MOUNT STOP L MATICS MODEM • PERIMETER ALARM • SECURE PKG 1 YR INCLUI • SOS POST-CRASH ALERT		Appual fuel Cost Fuel Economy
 POWER TAILGATE LOCK REAR PRIVACY GLASS TRAILER SWAY CONTROL WIPERS- INTERMITTENT ZONE LIGHTING 	D	 PRE-COLLISION ASSIST W/. REVERSE BRAKE ASSIST REVERSE SENSING AND REAR VIEW CAMERA SELECTABLE DRIVE MODES SYNC®4 W/EVR & 12" SCRE 	WARRANTY • 3YR/36,000 BUMPER • 5YR/60,000 POWERT	7 bumper Train De Assist	\$2,6000 This vehicle emits 452 distributing fuel also crower of the average new vehicle gets 28 MPG and costs \$9,50 based on 15,000 miles per year at \$3,50 per gallon. MPGe is memissions are a significant cause of climate change and smog.
INCLUDED ON THIS VEHICLE	(MSRP)			(MSRP)	emissions are a significant cause of climate change and smog.
EQUIPMENT GROUP 302A •XLT SERIES •LED SIDE-MIRROR SPOTLIGHTS •POWER-SLIDING REAR WINDOW	7,440.00	BASE TOTA	E INFORMATION PRICE L OPTIONS/OTHER	\$48,055.00 13,065.00	fueleconomy.gov Calculate personalized estimates and compare vehicles
OPTIONAL EQUIPMENT/OTHER	(Try		L VEHICLE & OPTIONS/OTHER	61,120.00 2,195.00	GOVERNMENT 5-STAR SAFETY
2025 MODEL YEAR RAPID RED MET TINTED CC .EXTENDED RANGE 36GAL FUEL TAN 3.5L V6 ECOBOOST 275/60R20 BSW ALL-SEASON 3.55 MAX TOW E-LOCK REAR AXLE 7100# GVWR PACKAGE FRONT LICENSE PLATE BRACKET 6" BRIGHT ANODIZED STEP BAR 50 STATE EMISSIONS TOW/HAUL PACKAGE .INTEGRATED TRAILER BRAKE CONT MIRROR MAN FOLD W/POWER GLASS 20" CHROME-LIKE PVD WHEELS	495.00 2,220.00 NO CHARGE 395.00	XLT	AL BEFORE DISCOUNTS MID DISCOUNT AL SAVINGS	63,315.00 - 2,000.00 - 2,000.00	Overall Vehicle Score $\star \star \star$ Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size a
	NO CHARGE NO CHARGE 1,010.00				Frontal CrashDriver Passenger* * *Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size a
	1,505.00				SideFront seatCrashRear seatBased on the risk of injury in a side impact.
					Rollover $\star \star \star$ Based on the risk of rollover in a single-vehicle crash.
					Star ratings range from 1 to 5 stars (★★★★), wi Source: National Highway Traffic Safety Admini www.safercar.gov or 1-888-327-42
	RAMP ONE CH32		ŕ	315.00	
	RAMP TWO		Scan The QR Code to		WARNING: Operating, servicing and maintaining a pass
	2		this vehicle	WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine expose lead, which are known to the State of California to cause cance	

This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.

SF182 N RB 2X 565 005212 06 18 25

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phtl lead, which are known to the State of California to cause cancer and birth defects or other reproductive narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.



2202506290031